



**RETURN BIDS TO:
RETOURNER LES SOUMISSIONS A:
Bid Receiving/Réception des
sousmissions**

**RCMP / GRC
Procurement & Contracting services
c/o Commissionaires, F Division
6101 Dewdney Avenue
Regina, SK S4P 3K7**

**Facsimile Number for Amendments:
(306) 780-5232**

**SOLICITATION AMENDMENT
MODIFICATION DE L'INVITATION**

**The referenced document is hereby
revised; unless otherwise indicated, all
other terms and conditions remain the
same.**

**Ce document est par la présente révisé;
sauf indication contraire, les modalités
de l'invitation demeurent les memes.**

Comments - Commentaries

**Vendor/Firm Name and Address
Raison sociale et adresse du
fournisseur/de l'entrepreneur**

Facsimile No. - No de télécopieur:

Telephone No. - no de téléphone:

Title-Sujet Fire Wall and Roof Upgrades	
Solicitation No. - No. de l'invitation M5000-18-6323/A	Date 23 April 2018
Amendment No. - No modif. 02	
Client Reference No. - No. De Référence du Client M5000-18-6323/A	
GETS Reference No. - No. de Référence de SEAG PW-18-00823595	
Solicitation Closes -L'invitation prend fin at - à 2 :00 pm Central Standard Time on - le 30 April 2018	
F.O.B. - F.A.B. Destination	
Address Enquiries to: - Adresser toutes questions à: Teresa Hengen, Contracting Officer	
Telephone No. - No de téléphone (639) 625-3449	Fax No. - N° de FAX: (306) 780-5232
Destination of Goods, Services, and Construction: Destinations des biens, services et construction: Royal Canadian Mounted Detachment 12230 Main Ave Chateh, AB T0H 0S0	
This document does not contain a PERSONNEL SECURITY Clearance requirements	
Delivery Required - Livraison exigée: See Herein Voir aux présentes	Delivery Offered - Livraison proposée
Name and title of person authorized to sign on behalf of Vendor/Firm Nom et titre de la personne autorisée à signer au nom du fournisseur/de l'entrepreneur	



This amendment is to answer the following:

Q1. Also how much mold remediation is required, the whole under side of the roof has water stains everywhere in the attic space? The attic space is insulated, not sure if you need more insulation or not? If the roof was not done right originally, there could be condensation under the entire metal roof? I don't know but maybe there could be cash allowances for mold remediation, insulation in attic space.

R1. The main issue is the water infiltration into the detachment. There may be a requirement to replace some roof sheeting due to water damage. Mould re-mediation is required in the area effected by water infiltration only. If additional mould re-mediation is required, this will be dealt with by contract amendment. There is a requirement to verify attic insulation and install additional insulation where required. There may be insulation gaps in the attic space that have not been addressed since the construction which may contribute to water condensation which would contribute to moisture issues. Any major problems, outside the scope of this project, identified during the construction phase will be addressed through a contract amendment.

Q2. Does there need to be a warranty provided?

R2. Yes, typical 12 month warranty is to be provided as per GC3.13.

Q3. What happens if the block wall crumbles when we try to attach materials, via drilling and smack pins?

R3. In the event the block wall crumbles, replacement will be required and a contract amendment will address this.

Q4. If roof metal cannot be reused, are they prepared to re-do the complete roof?

R4. Yes. This will be addressed through the use of a contract amendment.

Q5. Are there existing drawings, O&M Manuals, Shop drawings that we could look at?

R5. Yes. Roofing as built attached separately.

ALL OTHER TERMS AND CONDITIONS REMAIN THE SAME