

Solicitation No. - N° de l'invitation  
ET025-183260/A

Amd. No. - N° de la modif.  
005

Buyer ID - Id de l'acheteur  
pwz117

Client Ref. No. - N° de réf. du client  
INAC

File No. - N° du dossier  
PWZ-7-40287 (117)

CCC No./N° CCC - FMS No./N° VME

---

Public Works and Government Services Canada	New Daycare Iqaluit, Nunavut Solicitation # ET025-183260/A	Page 1 of 1
R082769.001		April 30, 2018

---

**Question:** "Can you please find out for me where the machine room for the wheelchair lift will be located? By code we need a dedicated room for the elevator equipment. Please refer yourself to the attached document for all the details."

**Clarification:** The wheelchair lift does not require a machine room as it is not a passenger elevator or dumbwaiter per NBC. Its installation must be conform to CSA 355 which does not specify particular requirements with regards to the controls being separated from the remainder of the building. Refer to electrical plans for location of control equipment.