



ITEM ID	QTY	MODEL CODE	DESCRIPTION	MANUFACTURER
13	1	1803	Breather	
15	1	FP101S295	Priority Flow Control	Parker
16	1	50AT10CN250OH	Filter	Parker
21	2	SDM080	Directional Control Valve	Walvoil
22	1	SDM080	Directional Control Valve	Walvoil
24	1	BMSY-100-E2-G-S	Winch Motor	Anfield
25	2	HYS 20MAL40-10	Cylinder Hydraulic	Hy-Spec
25	1	PL-5	Winch	Pullmaster
26	1	AP-F20-25/25-P1-L	Pump Fixed Double	Anfield
26f	1	FS-371-6FP	Female Quick Connect	Parker
26m	2	FS-372-6FP	Male Quick Connect	Parker
27f	3	SH4-62	Female Quick Connect	Parker
27m	4	SH4-63	Male Quick Connect	Parker
28f	2	SH3-62	Female Quick Connect	Parker
28m	3	SH3-63	Male Quick Connect	Parker
30	1	M10A.12	Crane	Fassi
31	1	AS04G2222	Unloading/Relief Valve	Parker

Note:
Failure to disengage Davit when it is disconnected
may cause hydraulic fluid to overheat