



REMOVE EXISTING HAZARD TREE REFER TO L-100 AND HAZARD TREE ASSESSMENT REPORT FOR BEST PRACTICES

H35

SEED BOTH SIDES OF BERM WITH SEED MIX #1 - SEE NOTES ON L-100

SUPPLY AND INSTALL SECTION OF TRAIL ON BERM. TRAIL TO BE CONSTRUCTED AS PER DETAIL 1/L-500. FENCING ON TO BE INSTALLED AS PER DETAIL 4/L-510

NOTE: FENCE SHALL STOP AND RE-START ON EITHER SIDE OF THE TRAIL AT SPILLWAY LOCATION CONSTRUCTED BY TRCA. DIMENSION OF GAP IN FENCE IS TO BE DETERMINED ON SITE

LEGEND



ADDENDUM #1
REVISION

TRAIL CONSTRUCTION ON EXISTING CLAY BERM - REVISED SHEET L-326

wsp Landscape Architecture
 100 Commerce Valley Dr W
 Thornhill, ON L3T 0A1
 t. 905-882-8000
 www.wsp.com

SK-2

SEPTEMBER 17, 2019