Public Works and	Stony Mountain, Manitoba	Addendum No. 1
Government Services	Stony Mountain Institution	Page 1 of 27
Canada	Building C12 – Powerhouse Repairs	-

Project No.: R.109027.001 October 8, 2020

The following changes to the tender documents are effective immediately and will form part of the contract documents:

Pictures of existing site conditions taken during site walk through. Emphasis on wall surfaces with various services throughout, which will require the installation of the structural steel bracing.



Picture 1 Showing Building Exterior, East

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 2 of 27



Picture 2 Showing Along Building Exterior, East

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 3 of 27



Picture 3 Showing Exterior Concrete Apron

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 4 of 27



Picture 4 Showing Along Exterior, East

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs


Addendum No. 1 Page 5 of 27



Picture 5 Showing Electrical Room, above Coal Vaults

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 6 of 27



Picture 6 Showing Electrical Room, above Coal Vaults

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 7 of 27



Picture 7 Showing Electrical Room, above Coal Vaults

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 8 of 27



Picture 8 Showing Generator Room, above Coal Vaults

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 9 of 27



Picture 9 Showing Garage, above Coal Vaults

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs


Addendum No. 1 Page 10 of 27



Picture 10 Showing Generator Room, above Coal Vaults

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 11 of 27



Picture 11 Showing Beam to be Repaired

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 12 of 27



Picture 12 Showing path leading to sub basement staircase

Public Works and Stony Mountain, Manitoba
Government Services Stony Mountain Institution
Canada Building C12 – Powerhouse Repairs


Addendum No. 1 Page 13 of 27



Picture 13 Showing sub basement from top of stair perspective

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 14 of 27



Picture 14 Showing sub basement from mid stair case

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 15 of 27



Picture 15 Showing sub-basement wall

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 16 of 27



Picture 16 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 17 of 27



Picture 17 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs


Addendum No. 1 Page 18 of 27



Picture 18 Showing sub basement walls and equipment

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 19 of 27



Picture 19 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 20 of 27



Picture 20 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 21 of 27



Picture 21 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 22 of 27



Picture 22 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 23 of 27



Picture 23 Showing sub basement walls

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs


Addendum No. 1 Page 24 of 27



Picture 24 Showing main floor access panels above sub basement

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 25 of 27



Picture 25 Showing main floor access panels above sub basement

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs

Addendum No. 1 Page 26 of 27



Picture 26 Showing main floor access panels above sub basement

Stony Mountain, Manitoba Stony Mountain Institution Building C12 – Powerhouse Repairs Addendum No. 1 Page 27 of 27

Project No.: R.109027.001 October 8, 2020



Picture 27 Showing main floor access panels, perspective looking up from sub basement

END OF ADDENDUM NO. 1