

**RETURN BIDS TO:**  
**RETOURNER LES SOUMISSIONS À:**  
**Public Works Government Services Canada- Bid**  
**Receiving / Réception des soumissions**  
**189 Prince William Street**  
**Room 421**  
**Saint John**  
**New Brunswick**  
**E2L 2B9**

## **SOLICITATION AMENDMENT MODIFICATION DE L'INVITATION**

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Solicitation remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'invitation demeurent les mêmes.

### **Comments - Commentaires**

**Vendor/Firm Name and Address**  
**Raison sociale et adresse du**  
**fournisseur/de l'entrepreneur**

**Issuing Office - Bureau de distribution**  
**Public Works Government Services Canada- Bid**  
**Receiving / Réception des soumissions**  
**189 Prince William Street**  
**Room 421**  
**Saint John**  
**New Bruns**  
**E2L 2B9**

<b>Title - Sujet</b> General Purpose Bldg-N.B./N.S.	
<b>Solicitation No. - N° de l'invitation</b> EC016-123090/A	<b>Amendment No. - N° modif.</b> 014
<b>Client Reference No. - N° de référence du client</b> R.043958.001	<b>Date</b> 2012-05-14
<b>GETS Reference No. - N° de référence de SEAG</b> PW-\$PWB-007-3063	
<b>File No. - N° de dossier</b> PWB-1-34209 (007)	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> <b>on - le 2012-05-29</b>	<b>Time Zone</b> <b>Fuseau horaire</b> Atlantic Daylight Saving Time ADT
<b>F.O.B. - F.A.B.</b> <b>Plant-Usine:</b> <input type="checkbox"/> <b>Destination:</b> <input type="checkbox"/> <b>Other-Autre:</b> <input type="checkbox"/>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Ellis-Herring , Alison PWB	<b>Buyer Id - Id de l'acheteur</b> pwb007
<b>Telephone No. - N° de téléphone</b> (506) 636-3908 ( )	<b>FAX No. - N° de FAX</b> (506) 636-4376
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b>	

**Instructions: See Herein**

**Instructions: Voir aux présentes**

<b>Delivery Required - Livraison exigée</b>	<b>Delivery Offered - Livraison proposée</b>
<b>Vendor/Firm Name and Address</b> <b>Raison sociale et adresse du fournisseur/de l'entrepreneur</b>	
<b>Telephone No. - N° de téléphone</b> <b>Facsimile No. - N° de télécopieur</b>	
<b>Name and title of person authorized to sign on behalf of Vendor/Firm</b> <b>(type or print)</b> <b>Nom et titre de la personne autorisée à signer au nom du fournisseur/</b> <b>de l'entrepreneur (taper ou écrire en caractères d'imprimerie)</b>	
<b>Signature</b>	<b>Date</b>

---

This Solicitation Amendment Number Fourteen (14) is raised to include the following questions and answers.

The following Addendum to the tender documents is effective immediately. This Addendum shall form part of the contract documents.

**All other terms and conditions remain the same.**

**Addendum No. 14**

**QUESTIONS AND ANSWERS**

Q1

Where is room A408 in Main Building?

A1

Room A408 is on the second floor, near the area above MCCP.

Q2

Reference Terms of Reference 5.5.14.1 b: Drawing R.043958.001 instructs the fire alarm fiber optic connection is from the GO building to the principal entrance building. This section instructs to connect to the MCCP in the main building. Please clarify.

A2

Connection shall be to the main panel in the MCCP.

Q3

Reference Terms of Reference 5.5.14.1 d: Is there a drawing available that shows where the existing underground spare conduits are?

A3

No.

Q4

Reference Terms of Reference 5.5.14.1 f: How many annunciators require updating?

A4

There is 1 graphic annunciator in the MCCP at Atlantic Institution that requires updating.

---

Q5

Reference Terms of Reference 5.5.14.1 g: Require a common alarm and trouble between FAAS in MCCP to new FACP. This connection is not indicated on R.043958.001. Is this to be an additional underground conduit between the GO building and the main building? Is this typical for both buildings?

A5

Delete reference to connection between the Fire Alarm Panel and the FAAS.

Q6

Reference Terms of Reference 5.5.15.1 a: Is this typical for both buildings? According to drawing R.043958.001 the telephone entrance appears to be in the principal entrance building and not the main building. This appears to conflict.

A6

The PA head-end is located in the CER, adjacent to the MCCP, at both Institutions.  
The telephone entrance is located in the Principal Entrance in both Institutions.

Q7

Are the fire extinguishers to be mounted in wall cabinets in these two buildings? Please clarify.

A7

Please see Terms of Reference section 5.6.6.1.i, this applies to the entire GI building.

Q8

Are institutional style sprinkler heads required in these two buildings and if so will they be required in all areas? Please clarify.

A8

No.