


USED ON



SECTION THREE PLODED LOOKING TWO

INDICES

1) 175.00 - 140.40 = 10 THE BACKING
TO BE WELDED TO SPLIT PLAS
BEFORE PPLS ARE WELDED IN PLACE.

25. IF IN DOUBT - ASK.

[illegible]


545

| N# | | LOC | DESCRIPTION | APP | DATE |
|-----------|--|-----|-------------|-----|------|
| REVISIONS | | | | | |

| | | |
|----------------|----|------------------------------|
| JOB OR HULL NO | 27 | OFFSHORE TUG / SUPPLY VESSEL |
|----------------|----|------------------------------|

TITLE "BOOK RECESS FOR
MACHINING: BAD"

| | | | | | | |
|-------|-----------|--|---------|------------|--|-----------------------------|
| 155 | APPROVALS | | SCALE | 1-25 | | DRAWING NO 37-010-09-441 |
| | OWNERS | | DRAWN | 40 | | |
| | MAT AUTH | | DATE | 20-0-95 | | |
| | CLASS SO | | CHECKED | | | |
| OTHER | | | DATE | SHT / OF 1 | | REV 0 |



MARYSTOWN
SHIPYARD LIMITED
MARYSTOWN NEWFOUNDLAND