

## RETURN BIDS TO:

## RETOURNER LES SOUMISSIONS À:

Public Works and Government Services / Travaux  
publics et services gouvernementaux  
Kingston Procurement  
Des Acquisitions Kingston  
86 Clarence Street, 2nd floor  
Kingston  
Ontario  
K7L 1X3  
Bid Fax: (613) 545-8067

## Revision to a Request for a Standing Offer

## Révision à une demande d'offre à commandes

Regional Individual Standing Offer (RISO)

Offre à commandes individuelle régionale (OCIR)

The referenced document is hereby revised; unless  
otherwise indicated, all other terms and conditions of the  
Offer remain the same.

Ce document est par la présente révisé; sauf indication  
contraire, les modalités de l'offre demeurent les mêmes.

## Comments - Commentaires

## Vendor/Firm Name and Address

Raison sociale et adresse du  
fournisseur/de l'entrepreneur

## Issuing Office - Bureau de distribution

Public Works and Government Services / Travaux  
publics et services gouvernementaux  
Kingston Procurement  
Des Acquisitions Kingston  
86 Clarence Street, 2nd floor  
Kingston  
Ontario  
K7L 1X3

<b>Title - Sujet</b> Tower Structures- Repair and mainte	
<b>Solicitation No. - N° de l'invitation</b> W0125-13K260/A	<b>Date</b> 2013-07-31
<b>Client Reference No. - N° de référence du client</b> W0125-13-K260	<b>Amendment No. - N° modif.</b> 006
<b>File No. - N° de dossier</b> KIN-3-40014 (655)	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>GETS Reference No. - N° de référence de SEAG</b> PW-\$KIN-514-6125	
<b>Date of Original Request for Standing Offer</b> 2013-05-29	
<b>Date de la demande de l'offre à commandes originale</b>	
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> <b>on - le 2013-08-16</b>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Semple, Patrick	<b>Buyer Id - Id de l'acheteur</b> kin655
<b>Telephone No. - N° de téléphone</b> (613) 530-3117 ( )	<b>FAX No. - N° de FAX</b> (613) 545-8067
<b>Delivery Required - Livraison exigée</b>	
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b>	
<b>Security - Sécurité</b> This revision does not change the security requirements of the Offer. Cette révision ne change pas les besoins en matière de sécurité de la présente offre.	

Instructions: See Herein

Instructions: Voir aux présentes

<b>Acknowledgement copy required</b> <b>Accusé de réception requis</b>	<b>Yes - Oui</b> <input type="checkbox"/>	<b>No - Non</b> <input type="checkbox"/>
<b>The Offeror hereby acknowledges this revision to its Offer.</b> <b>Le proposant constate, par la présente, cette révision à son offre.</b>		
<b>Signature</b>	<b>Date</b>	
Name and title of person authorized to sign on behalf of offeror. (type or print) Nom et titre de la personne autorisée à signer au nom du proposant. (taper ou écrire en caractères d'imprimerie)		
<b>For the Minister - Pour le Ministre</b>		

Further information regarding questions in Amendment #004.

**1)** Please provide the total number of SRL's that require replacement. The contract documents do not give same. At the site meeting the Technical Authority stated that upon removal the SRL had to be replaced immediately. However the documents do not state same.

Answer:

The number of SRL's that require replacement are below. All SRL's below must be inspected in the 1st year of contract, including those in Hangar's 1 & 2.

Type	Location	Remarks	Number of SRL'S
ManSafe System	Bldg B052, Hangar 10, Bays 3,4,5,6	SRL replacements required	69
ManSafe System	Bldg B112, Hanger 9, Main floor	SRL replacements required	35
ManSafe System and Fixed Roof Tie-off	New Hangar 1	As Per Attached Drawings SRL replacements required	82
ManSafe System and Fixed Roof Tie-off	New Hangar 2	As Per Attached Drawings SRL replacements required	48
ManSafe System	Bldg 522 (152 Meters)	As per Attached Drawing SRL replacements required	6

(b) Description of this Work will be added to the SOW as follows:

**Refer:** Annexe A, Section B, 4. Work Included c. Yearly inspection of Fall Protection Systems.

**Insert:** C. 6. Upon removal SRL's must be replaced immediately at the Sites where it is indicated in the remarks section of Annex "B". Minimum of 25 SRL's to be removed and replaced at any one time.

**2)** In order to bid please provide us with building drawings showing the location of the SRL's and distance or height from finish floor to the SRL's.

(b) Additional Information on ceiling heights below...

Height of Ceiling in Hangars. (underside deck)

B52 – 18.26 – 20.7 metres,

B112 – 9.25 metres,

B522 – 20.1 metres, 23.2 metres,

B607 – 17.5 metres

Solicitation No. - N° de l'invitation

W0125-13K260/A

Amd. No. - N° de la modif.

006

Buyer ID - Id de l'acheteur

kin655

Client Ref. No. - N° de réf. du client

W0125-13-K260

File No. - N° du dossier

KIN-3-40014

CCC No./N° CCC - FMS No/ N° VME

---

B587 - 13.5m/8.4m unobstructed / 12m/7m obstructed