

**RETURN BIDS TO:**  
**RETOURNER LES SOUMISSIONS À:**  
**Bid Receiving - PWGSC / Réception des soumissions**  
**- TPSGC**  
**11 Laurier St. / 11, rue Laurier**  
**Place du Portage, Phase III**  
**Core 0A1 / Noyau 0A1**  
**Gatineau, Québec K1A 0S5**  
**Bid Fax: (819) 997-9776**

## SOLICITATION AMENDMENT MODIFICATION DE L'INVITATION

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Solicitation remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'invitation demeurent les mêmes.

### Comments - Commentaires

**Vendor/Firm Name and Address**  
**Raison sociale et adresse du**  
**fournisseur/de l'entrepreneur**

**Issuing Office - Bureau de distribution**  
Defence Communications Division. (QD)  
11 Laurier St./11, rue Laurier  
Place du Portage, Phase III, 8C2  
Gatineau, Québec K1A 0S5

<b>Title - Sujet</b> ruggedized router communications sy	
<b>Solicitation No. - N° de l'invitation</b> W6399-13EC51/A	<b>Amendment No. - N° modif.</b> 003
<b>Client Reference No. - N° de référence du client</b> W6399-13EC51	<b>Date</b> 2014-03-12
<b>GETS Reference No. - N° de référence de SEAG</b> PW-\$\$QD-019-24338	
<b>File No. - N° de dossier</b> 019qd.W6399-13EC51	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> <b>on - le 2014-03-20</b>	<b>Time Zone</b> <b>Fuseau horaire</b> Eastern Daylight Saving Time EDT
<b>F.O.B. - F.A.B.</b> <b>Plant-Usine:</b> <input type="checkbox"/> <b>Destination:</b> <input checked="" type="checkbox"/> <b>Other-Autre:</b> <input type="checkbox"/>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Ruest, Luc	<b>Buyer Id - Id de l'acheteur</b> 019qd
<b>Telephone No. - N° de téléphone</b> (819) 956-7113 ( )	<b>FAX No. - N° de FAX</b> (819) 956-0636
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b>	

**Instructions: See Herein**

**Instructions: Voir aux présentes**

<b>Delivery Required - Livraison exigée</b>	<b>Delivery Offered - Livraison proposée</b>
<b>Vendor/Firm Name and Address</b> <b>Raison sociale et adresse du fournisseur/de l'entrepreneur</b>	
<b>Telephone No. - N° de téléphone</b> <b>Facsimile No. - N° de télécopieur</b>	
<b>Name and title of person authorized to sign on behalf of Vendor/Firm</b> <b>(type or print)</b> <b>Nom et titre de la personne autorisée à signer au nom du fournisseur/</b> <b>de l'entrepreneur (taper ou écrire en caractères d'imprimerie)</b>	
<b>Signature</b>	<b>Date</b>

Solicitation No. - N° de l'invitation

W6399-13EC51/A

Amd. No. - N° de la modif.

003

Buyer ID - Id de l'acheteur

019qd

Client Ref. No. - N° de réf. du client

W6399-13EC51

File No. - N° du dossier

019qdW6399-13EC51

CCC No./N° CCC - FMS No/ N° VME

---

See attached Questions and Answers.

**All other terms and conditions remain unchanged.**

Questions and Answers for solicitation number W6399-13EC51/A

Question 1:

Ref.: Part 7 Section 2.2 Supplemental General Conditions references 4001 (2013-06-27) Hardware, Purchase, Lease and Maintenance. 4001 subsection 05 in turn states “unless otherwise provide in the Contract, the Contractor must unpack, assemble, install, integrate, interconnect, and configure all the Hardware at the location(s) specified in the Contract.”

**Is it the Crown’s intention to have the Contractor complete the activities referenced above?**

Answer 1:

It is not Canada’s intention to have the Contractor complete the activities in SACC 4001 subsection 05.

Question 2:

Reference: Annex A, Section 3.1 (b) Operator/Maintenance Manual, where it states “The maintenance manual is to include all first and second line repairs of the device ...”.

The maintenance concept is based upon remove and replace at 1st line and forward to the OEM at 3rd line for repair. The maintenance program does not include provision for 2nd line repair. 2nd line repairs are deemed infeasible economically due to cost of parts, labour, training, etc. However, initial setup and configuration of the modules can be accomplished either at 1st or 2nd line.

**Please confirm that 2<sup>nd</sup> line repairs will not be conducted.**

Answer 2:

DND accepts that, if the maintenance concept is repair by replacement at first line and OEM at third, there is no second line repair to be included in the maintenance manual.