



Q&A #2

Date: July 07, 2014

Project: 01B46-14-0054- Feasibility study plans and specifications preparation and work monitoring for the repair of the roof of building No. 35.

Bidders must make sure that their bids are based on the latest version of the tender documents published and take into consideration the following amendments and information, including any information provided on amendments or Q&As previously published for this project.

Bidders that do not comply with this requirement will be discarded.

Please note: In order to provide the integrity of the questions that AAFC has received from bidders, you will find in this document the questions in the language that they were asked.

Questions and answers:

Q2- The repairs to consider are for the roof or there are also structural repairs (architecture and/or engineering)?

A2- The repair works are considered architectural ones. There are no structural repairs within the scope of this project.

Q3- It would be interesting to see plans before the meeting.

A3- Attached pictures of the building are available before the site visit.

ALL OTHER TERMS AND CONDITIONS REMAIN UNCHANGED

MAIN BUILDING PICTURES



Rear view – East



Rear view – West



Front view – West



Front view – Center



Front view – East



Flat roof front view – West



Flat roof front view – West



Flat roof front view – East



Flat roof front view – East



Flat roof rear view – East



Flat roof rear view – East



Flat roof rear view – East



Flat roof rear view – East