

Solicitation No. – N° de l’invitaion  
EA011-160223/A

Amd. No. - N° de la modif.  
7

Buyer ID – Id de l’acheteur  
pwd005

Client ref. No. - N° de ref. du client  
R.060181.001

File No. N° du dossier  
PWD-5-38046 (005)

CCC No./N° CCC – FMS No/N° VME

---

ADDENDUM NO. 6

R.060181.001 – North West River Bridge Replacement, Terra Nova National Park, NL

\*\*\*\*\*

**THE FOLLOWING AMENDMENT TO THE BID DOCUMENTS IS EFFECTIVE IMMEDIATELY. THE  
ADDENDUM SHALL FORM A PART OF THE CONTRACT DOCUMENTS.**

\*\*\*\*\*

.1 Queries/Responses:

Query 1: “SSP Retaining Wall structure – there is no specific item for this thus we presume it is to be included in the LSA – the groundwork’s to facilitate the installation (clearing, grubbing, excavation etc) - particularly on opposite side of existing highway for the deadmen installation – will this be paid under applicable unit price items or are bidders to include for this in the LSA also?”

Response 1: Section 31 62 16.13 Steel Sheet Piles – Temporary Retaining Walls and Construction Phasing (PH) drawings specify the requirements of the SSP (temporary) retaining wall structure. All work described and shown on the drawings is included under this item. All work to complete this item is included in the lump sum price.

Query 2: “Underpass Retrofit – similar to above – the groundwork’s (excavation, pathway removal, pathway reinstatement etc) - will this be paid under applicable unit price items or are bidders to include for this in the LSA also?”

Response 2: Section 05 55 00 Design & Build Underpass Retrofit and Structural Steel Plate Underpass Retrofit Phasing (U) drawings specify the requirements of the underpass structure and the work included under this item. As per Clause 1.2.2 all work to complete this item is included in the lump sum price.

Query 3: “Proposed parking lot and pathway to/from new bridge structure – we interpret that this work (quantities) will be paid for under applicable items from the unit price table – please confirm.”

Response 3: Quantities of materials for the construction of the parking lot and pathway have been included in items listed in the Unit Price Table.

Solicitation No. – N° de l’invitaion  
EA011-160223/A

Amd. No. - N° de la modif.  
7

Buyer ID – Id de l’acheteur  
pwd005

Client ref. No. - N° de ref. du client  
R.060181.001

File No. N° du dossier  
PWD-5-38046 (005)

CCC No./N° CCC – FMS No/N° VME

- 
- Query 4: “Under which item is the imported material required to build the subgrade for new highway alignment included – is this combination of item 20 – common fill and item 23 – granular sub base?”
- Response 4: Quantities of materials for the construction of the roadway subgrade have been included in items listed in the Unit Price Table.
- Query 5: “Realignment of waterway – we interpret that this work (quantities) will be paid for under applicable items from the unit price table – please confirm.”
- Response 5: Quantities for realigning the waterway (ditch) have been included in items listed in the Unit Price Table.
- Query 6: “Drawing C04 shows a typical detail for topsoil and sod – please confirm extent of this work.”
- Response 6: Topsoil and sodding is limited on this project to the areas of reinstatement along the golf path to be restored under Section 05 55 00 Design & Build Underpass Retrofit, where necessary.

**By submission of its bid, the Bidder confirms that it has read and understands the requirements expressed in all addenda and has included all costs of these requirements in its Total Bid Amount.**

\*\*\*\*\*