

Annex C - Hoses and extinguisher inventory

Location	Model	Year made	Serial #	Make	Last Hydro Test	Next Hydro Test	Next (6 year) Maintenance
Exterior							
UPS shed exterior	ABC 10	1995	36473	Strike First	2007	2019	2015
South east gate (diesel tank)	ABC 20	2011	407679	Strike First		2023	2017
185 ton chiller	CO2 10	1998	4857	Strike First	2010	2015	(37lb)
25kv room	ABC 10	2010	673138	Ansul		2022	2016
6th Floor							
Office 7.1	ABC 5	1991	97539	Flag	2003	2015	2016
Mecanical room 6.05	ABC 10	2013	160702	Ansul		2025	2019
Pump room 6.04	ABC 20	2007	750414	Amerex		2019	2019
Pump room 6.04 (emergency boguey)	ABC 10	2009	291380	Strike First		2021	2015
Mecanical room 6.06	ABC 20	2007	750423	Amerex		2019	2019
Lunch room 6th	ABC 5	2009	75412	Ansul		2021	2015
Workshop 6.08	ABC 10	2007	699376	Amerex		2019	2019
Tank cooling tower-2	ABC 10	1993	245360	Strike First	2004	2016	2017
Reverse osmosis room	ABC 5	2009	75816	Ansul		2021	2015
Room chiller FR-2	ABC 10	2008	70078	Ansul		2020	2014
Mecanical room 6.01	ABC 20	2009	65725	Ansul		2021	2015
Emergency exit door 6th	ABC 10	1988	950721	Flag	2013	2025	2019
Elevator mecanical room	ABC 10	1992	239868	Strike First	2004	2016	2017
Mecanical room 6.01	Hose	1994	1 1/2 x 75'	Niedner	2013	2016	
Sprinkler section	ABC 10	2007	699185	Amerex		2019	2019
5th Floor							
RPN Administration 5.07	ABC 5	1988	124003	Flag	2006	2018	2019
Coffee corridor 5.06	ABC 5	1992	409821	Strike First	2004	2016	2017
5.03	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Electrical room men washroom Local 550-1	C02-5 Class 5BC	11-2009	562188	Ansul		11-2014	(14lb)
Local 520 UPS	FE-09 1A10BC	2009	797036	Ansul		2021	2015
Emergency exit 557 5.08	ABC 5	2006	140794	Amerex		2018	2019
Photocopier corridor	ABC 5	2009	75804	Ansul		2021	2015
Fire Cabinet 5.01	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Location	Model	Year made	Serial #	Make	Last Hydro Test	Next Hydro Test	Next (6 year) Maintenance
Elevator 5.05	ABC 5	1992	409834	Strike First	2004	2016	2017
4th Floor							
Emergency exit 457 4.07	ABC 5	2006	140798	Amerex		2018	2019
Room 436 4.01	ABC 10	1992	239870	Strike First	2004	2016	2017
Fire Cabinet elevator 4.02	ABC 10	2002	67470	Strike First		2014	2015
Fire Cabinet elevator 4.02	Hose	2007	1 1/2 x 75'	Polyflex	2013	2016	

Next to room 410 4.06	ABC 10	2006	543575	Amerex		2018	2019
Next to washroom 4.04	ABC 10	2002	67460	Strike First		2014	2015
<i>Next to washroom 4.04</i>	Hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Electrical room men's washroom Local 450-1	C02-5 Class 5BC	11-2009	562203	Ansul		11-2014	(14lb)
Office 412 4.06	ABC 10	1992	239859	Strike First	2004	2016	2017
<u>3rd Floor</u>							
Fire cabinet 3.03	ABC 10	2002	67469	Strike First		2014	2015
<i>Fire cabinet 3.03</i>	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Electrical room men's washroom Local 350-1	C02-5 Class 5BC	11-2009	562201	Ansul		11-2014	(14lb)
Next to office 307 3.08	ABC 10	2007	699009	Amerex		2019	2019
Next to office 315 3.05	ABC 5	2007	357050	Amerex		2019	2019
Emergency exit 257 3.06	ABC 10	1993	245359	Strike First	2006	2018	2019
Office 335 3.07	ABC 5	2007	357044	Amerex		2019	2019
Fire cabinet 3.01	ABC 10	1992	239861	Strike First	2004	2016	2017
<i>Fire cabinet 3.01</i>	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
<u>2nd Floor</u>							
Emergency exit 2.10	ABC 10	2007	699378	Amerex		2019	2019
Fire cabinet 2.01	ABC 10	2002	67495	Strike First		2014	2015
<i>Fire cabinet 2.01</i>	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Office 212	ABC 5	2007	354797	Amerex		2019	2019
Washroom 2.04	ABC 10	1992	239884	Strike First	2004	2016	2017
<i>Washroom 2.04</i>	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Electrical room men's washroom Local 260-1	C02-5 Class 5BC	11-2009	562179	Ansul		11-2014	(14lb)
Room 212 2.00	FE-09 1A-10BC	2009	797027	Ansul		2021	2015
Location	Model	Year made	Serial #	Make	Last Hydro Test	Next Hydro Test	Next (6 year) Maintenance
Near office 214 2.06	ABC 10	1993	245362	Strike First	2006	2018	2019
<u>1st floor</u>							
Café Gueniève	Classe K Class 1 AK	2006	117704	Amerex	2011	2016	
Fire cabinet 1.13	ABC 10	2002	67484	Strike First		2014	2015
<i>Fire cabinet 1.13</i>	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Lunch room 1.14	ABC 10	1993	245368	Strike First	2009	2021	2015
Emergency exit	ABC 5	2008	72078	Ansul		2020	2014
Conference room 1.11	ABC 10	1993	245361	Strike First	2006	2018	2019
Conference room 1.20	ABC 10	1995	36478	Strike First	2006	2018	2019
Conference room 1.12	ABC 5	2001	215527	Amerex		2013	2019
Security	ABC 5	2007	357039	Amerex		2019	2017
Fire cabinet 1.01	FE-09 1A-10BC	2009	797026	Ansul		2021	2015
<i>Fire cabinet 1.01</i>	hose	2007	1 1/2 x 75'	Polyflex	2013	2016	
Administration	ABC 5	1986	597850	Diamond	2011	2023	2017

NETOPS 5.03	FE-09 1A-10BC	2009	797031	Ansul		2021	2015
<u>Basement #1</u>							
Elevator 01	ABC 20	2007	750427	Amerex		2019	2019
Emergency boguey ss	ABC 10	2009	291388	Strike First		2021	2015
Emergency boguey ss	ABC 10	2009	291390	Strike First		2021	2015
Room S-101 ss 1.5	ABC 20	2007	750415	Amerex		2019	2019
<u>SPARE</u>							
	C02 10 Class 10BC	1998	4869	Strike First	2009	2014	(35lb)
	C02 10 Class -BC	1986	286555	??	2013	2018	(32lb)
	ABC 5	1988	127604	Flag	2013	2025	2019
	C02 10 Class 10BC	1998	4832	Strike First	2009	2014	(34lb)
	ABC 10	1986	606102	Diamond	2011	2023	2017
Room S-102 ss. 16	ABC 10	1995	36485	Strike First	2009	2021	2015
Room SS. 108 ss.7	C02 20 Class 10BC	1972	96424	Kiddie	2009	2014	(53lb)
Corridor next to S-108 ss. 04	ABC 10	2007	699008	Amerex		2019	2019
Electrical room S-163 ss. 06	C02 10 Class 5BC	1971	60638	Flag	2009	2014	(34lb)
Location	Model	Year made	Serial #	Make	Last Hydro Test	Next Hydro Test	Next (6 year) Maintenance
Corridor next to S-163 ss. 05	C02 20 Class10BC	1985	401693	Flag	2013	2018	(44lb)
Room S-109	ABC 10	1992	239869	Strike First	2004	2016	2018
Room S-110	C02 10 Class 10BC	2001	794728	Pyrene	2011	2016	(26lb)
SS. 18 garage	ABC 10	2007	699184	Amerex		2019	2019
<u>GARAGE</u>							
Warehouse S-121	ABC 10	1988	970676	Flag	2013	2025	2019
Garage door	C02 10 Class 10BC	1998	4907	Strike First	2009	2014	(36lb)
Shop S-123 ss. 14	ABC 10	1992	239854	Strike First	2004	2016	2017
Recycling room ss. 19	ABC 10	1995	36484	Strike First	2007	2019	2019
Recycling room	ABC 10	1992	239853	Strike First	2004	2016	2017
Emergency exit S-167 ss. 02	ABC 10	2007	699065	Amerex		2019	2019
Bell room S-164 ss. 03	C02 10 Class 5BC	1980	176584	Pyrene	2013	2018	(27lb)
Bobcat	ABC 5	2008	894653	Ansul		2020	2014
Lift	ABC 5	2008	894652	Ansul		2020	2014
Garage	ABC 10	1995	36491	Strike First	2007	2019	2015
Next to DPPUPS	C02 20 Class10BC	1995	341604	Flag	2011	2016	(46lb)
<u>UPS</u>							
SS. 21 UPS	C02 15 Class10BC	1983	22252	Flag	2009	2014	(35lb)
SS. 22 UPS	C02 15 Class10BC	1983	22277	Flag	2009	2014	(35lb)

S-129	C02 15 Class10BC	1986	55090	Pyrene	2009	2014	(36lb)
OPPS							
Room S-130 OPPS ss. 30	C02 15 Class10BC	2008	655185	Ansul		2013	(36lb)
Room S-130 OPPS ss. 25	C02 15 Class10BC	1985	50563	Pyrene	2009	2014	(34lb)
Room S-130 OPPS	C02 15 Class10BC	1985	50651	Pyrene	2009	2014	(34lb)
Room S-130 OPPS ss. 24	C02 20 Class10BC	1996	431453	Flag	2009	2014	(47lb)
Room S-130 OPPS	C02 15 Class10BC	1985	50705	Pyrene	2009	2014	(35lb)
Room S-130 OPPS ss. 34	ABC 10	1992	239867	Strike First	2004	2016	2017
CENTRAL SERVERS							
S-119 ss. 37	ABC 10	2002	67489	Strike First		2014	2015
S-111 ss. 09	ABC 10	1993	245367	Strike First	2004	2016	2017
Location	Model	Year made	Serial #	Make	Last Hydro Test	Next Hydro Test	Next (6 year) Maintenance
Next to S-201 ss. 38	ABC 10	2002	67490	Strike First		2014	2015
Room S-200 ss. 39	Watermist Class 2AC	2003	282246	Amerex	2009	2014	
Column 9-10 X-Y	Watermist Class 2AC	2003	282212	Amerex	2009	2014	
Lab ss. 41	Watermist Class 2AC	2003	282213	Amerex	2009	2014	
Lab ss. 40	Watermist Class 2AC	2003	282207	Amerex	2009	2014	
Next to door S-204 IBM	C02 10 Class 10BC	1998	4876	Strike First	2009	2014	(36.5lb)
Column 37-38 GG-HH	Watermist Class 2AC	2003	282205	Amerex	2009	2014	
Column 24 ss. 44 X-Y	Watermist Class 2AC	2003	282237	Amerex	2009	2014	
Column 37-38 X-Y	Watermist Class 2AC	2003	282206	Amerex	2009	2014	
Column 51-52 X-Y	Watermist Class 2AC	2003	282250	Amerex	2009	2014	
Column 51-52 O-P ss.42	Watermist Class 2AC	2003	282211	Amerex	2009	2014	
Room S-210/209	ABC 5	2008	72085	Ansul		2020	2014
Room S-211	ABC 10	2008	70077	Ansul		2020	2014
Electrical room S-212	C02 10 Class10BC	1998	4872	Strike First	2009	2014	(34.5 lb)
Electrical room S-205 ss. 50	C02 10 Class10BC	1998	4927	Strike First	2009	2014	(36lb)
Emergency exit S-206 ss. 49	Watermist Class 2AC	2003	282238	Amerex	2009	2014	
Reception	ABC 10	2008	68594	Ansul		2020	2014