#### Environment Environnement Canada Canada

Back to home page

# Report

# **Tank System Information**

#### **Tank System Description**

EC #: 00001175 Internal Number

Description: Island Lake, MB - Large Tank

## **Contact Information**

### Owner

Royal Canadian Mounted Police 73 Leikin Dr M1-4 Mailstop #18 Ottawa Ontario K1A 0R2 Tel: (613) 843-5516 Fax: (613) 825-7518 **Tank Operator** Royal Canadian Mounted Police 73 Leikin Dr M1-4 Mailstop #18

Ottawa Ontario K1A 0R2 Tel: (613) 843-5516 Fax: (613) 825-7518

#### Contact

Rod Savard 11140-109 Street Edmonton Alberta Tel: (780) 670-8580

## Contact

Rod Savard 11140-109 Street Edmonton Alberta Tel: (780) 670-8580

#### Land Owner

Federal entity under Financial Administration Act

#### Months of service

January February March April Canada

May June July August September October November December

### **System Location**

#### **Tank System Location**

General Delivery Stevenson Island Manitoba

### System Record Location

General Delivery Stevenson Island Manitoba

### **Emergency Plan Location**

General Delivery Stevenson Island Manitoba Details:

# **Miscellaneous Information**

Tank Use:

Name of Tank Manufacturer:

Year of Manufacture:

Certification # of System Installer:

Certification # of System Remover:

# Tank 1 of 1

## **Tank Information**

Tank Description:

Tank Internal Number:

Type of Tank: Aboveground ULC or API Standard Number: ULC-S653 Year of installation: 1995 Material of construction: Steel Overfill Protection: • Method – trained personnel in attendance at all times Type of pump: No oil-water separator Spill Containment: Spill box at fill point (aboveground tank) Product Stored: Gasoline Tank Capacity: 15000 L Transfer area: Spill box, secondary containment provided at truck, trained personnel Tank Leak Detection: • Interstitial monitoring – double walled tank Corrosion Protection: • Painted

- Secondary Containment:
  - Double Walled

# Piping for tank 1

Type of Piping: Aboveground Piping diameter: 2 inch Piping Leak Detection: • Visual inspection Leak detection for sumps: • No sump for storage tank system Material of construction: • Steel Corrosion Protection: • Painted Secondary Containment: • None