

**GOVERNMENT OF CANADA
MULTI-PURPOSE TRAINING FACILITY MECHANICAL RENOVATION
REGINA, SASKATCHEWAN**

ISSUED BY

**NUMBER TEN ARCHITECTURAL GROUP
310 - 115 BANNATYNE AVENUE
WINNIPEG, MB R3B 0R3**

ALL BIDDER SHALL READ THE ENTIRE ADDENDUM AND TAKE INTO ACCOUNT AS PART OF THE TENDER DOCUMENTS.

WHERE A REVISION IS CALLED FOR IN A DRAWING OR IN A SECTION OF A SPECIFICATION, IT SHALL BE CONSIDERED REVISED FOR ALL RELATED DRAWINGS AND SECTIONS OF THE SPECIFICATION.

Contents

No. of Pages

Addendum No. 2

2

1.0 ARCHITECTURAL SPECIFICATIONS

1.1 Refer to Specification Section 09 90 00 Painting

.1 Refer to Part 3 Execution

.1 Add new Article 3.6 Finishing Mechanical and Electrical Equipment as follows: “3.6 FINISHING AND ELECTRICAL EQUIPMENT

- .1 Remove unfinished louvers, grilles, covers, and access panels on mechanical and electrical components and paint separately.
- .2 Prime and paint insulated and exposed pipes, conduit, boxes, insulated and exposed ducts, hangers, brackets, collars and supports, except where items are prefinished.
- .3 Paint interior surfaces of air ducts, and convector and baseboard heating cabinets that are visible through grilles and louvers with one coat of flat black paint, to visible surfaces. Paint dampers exposed behind louvers, grilles, and convector and baseboard cabinets to match face panels.
- .4 Paint exposed conduit and electrical equipment occurring in finished areas.
- .5 Paint both sides and edges of plywood backboards for electrical and telephone equipment.
- .6 Colour code equipment, piping, conduit, and exposed duct work in accordance with colour schedule. Colour band and identify with flow arrows names and numbering.
- .7 Reinstall electrical cover plates, hardware, light fixture trim, escutcheons, and fittings removed prior to finishing.”

2.0 ARCHITECTURAL DRAWINGS

2.1 Refer to Drawings A1.2 Main Floor Construction Plan and A1.3 Second Floor Construction Plan

- .1 Add General Note as follows: “Paint all new exposed mechanical and electrical services. Colour to match existing painted exposed services.”