


SLAB REINFORCING - MAIN OPERATING FLOOR												BEAM SCHEDULE																								
TYPE 1				TYPE 2				TYPE 3				TYPE 1				TYPE 2				TYPE 3																
BANDS	FORM	NO	DIAM	LENGTH	NO	DIAM	LENGTH	REMARKS	BANDS	FORM	NO	DIAM	LENGTH	NO	DIAM	LENGTH	REMARKS	BEAM	NO	DIAM	LENGTH	NO	DIAM	LENGTH	NO	DIAM	LENGTH	REMARKS	NO	DIAM	LENGTH	TYPE	NO	DIAM	LENGTH	REMARKS
M1	G	1	#5	24'-0"	1	#5	24'-0"		M100	G	1	#4	24'-0"	1	#4	24'-0"		B100	10-00	#4	18'-0"	#4	18'-0"	2	#4	18'-0"		10	#4	18'-0"	2	#4	18'-0"			



STRUCTURAL MAIN OPERATING FLOOR

SEPT 29/61 "AS BUILT"

103
 1 FEB 1966

R.C.G. M.S.L.
 MAX. 1/8" 16'x 16'

408

CONSULTING ENGINEER: RAYMOND C. GAUTHER, P.E., OSTA