

Solicitation No. - N° de l'invitation	Amd. No. - N° de la modif.	Buyer ID - Id de l'acheteur
EQ754-192006/B	01	pwl003
Client Ref. No. - N° de réf. du client VME	File No. - N° du dossier	CCC No./N° CCC - FMS No./N°
R.090211.001	PWL-8-41111	

Questions and Answers:

Q: Page 5 asks for cost breakdown in 3 days after acceptance. Page 9 asks for cost breakdown in 7 days after acceptance.

A: The cost breakdown clause in the summary of work should state 7 days, not 3 days.

Q: Page 26, Report not attached, Lead-Containing Coatings at Burlington Lift Bridge, Burlington, Ontario dated November 8, 2013 (attached at the end of this section)

A: See attachment 4 on Buyandsell.

Q: We hold a Designated Organization screening certificate but the majority of our personnel do not hold a reliability status. Is the lift bridge considered a "sensitive worksite" and therefore all employees working on the bridge would have to have individual reliability status?

A: Please refer to the SRCL document on Buyandsell, attachment 3 that states:

Unscreened personnel can be used for portions of the work but must be escorted by PSPC/PWGSC personnel.