



RETURN BIDS TO:

RETOURNER LES SOUMISSIONS À:

Bid Receiving Public Works and Government
Services Canada/Réception des soumissions/Travaux
publics et Services gouvernementaux Canada
See herein for bid submission
instructions/

Voir la présente pour les
instructions sur la présentation
d'une soumission

NA
Ontario

**SOLICITATION AMENDMENT
MODIFICATION DE L'INVITATION**

The referenced document is hereby revised; unless otherwise
indicated, all other terms and conditions of the Solicitation
remain the same.

Ce document est par la présente révisé; sauf indication contraire,
les modalités de l'invitation demeurent les mêmes.

Comments - Commentaires

Vendor/Firm Name and Address
Raison sociale et adresse du
fournisseur/de l'entrepreneur

Issuing Office - Bureau de distribution
Public Works and Government Services / Travaux
publics et services gouvernementaux
Kingston Procurement
Des Acquisitions Kingston
86 Clarence Street, 2nd floor
Kingston
Ontario
K7L 1X3

Title - Sujet Security Screening X-Ray Device Security Screening X-Ray Device (SSXD)	
Solicitation No. - N° de l'invitation W6776-210009/A	Amendment No. - N° modif. 001
Client Reference No. - N° de référence du client W6776-21-0009	Date 2022-05-20
GETS Reference No. - N° de référence de SEAG PW-\$KIN-930-8656	
File No. - N° de dossier KIN-1-56211 (930)	CCC No./N° CCC - FMS No./N° VME
Solicitation Closes - L'invitation prend fin at - à 02:00 PM Eastern Daylight Saving Time EDT on - le 2022-06-13 Heure Avancée de l'Est HAE	
F.O.B. - F.A.B. Specified Herein - Précisé dans les présentes Plant-Usine: <input type="checkbox"/> Destination: <input type="checkbox"/> Other-Autre: <input checked="" type="checkbox"/>	
Address Enquiries to: - Adresser toutes questions à: Littlefield, Mike	Buyer Id - Id de l'acheteur kin930
Telephone No. - N° de téléphone (613) 449-4206 ()	FAX No. - N° de FAX (613) 545-8067
Destination - of Goods, Services, and Construction: Destination - des biens, services et construction: Canadian Forces Postal Unit Headquarters Bldg 348 - 15 Westwin Ave. Trenton, Ontario	

Instructions: See Herein

Instructions: Voir aux présentes

Delivery Required - Livraison exigée	Delivery Offered - Livraison proposée
Vendor/Firm Name and Address Raison sociale et adresse du fournisseur/de l'entrepreneur	
Telephone No. - N° de téléphone Facsimile No. - N° de télécopieur	
Name and title of person authorized to sign on behalf of Vendor/Firm (type or print) Nom et titre de la personne autorisée à signer au nom du fournisseur/ de l'entrepreneur (taper ou écrire en caractères d'imprimerie)	
Signature	Date

Amendment 001 – is being issued in response to Offeror's questions and Canada's responses.

Q1: *Would it be acceptable if the system proposed has max object size of 595mm X 395mm (5mm) short in width, as the next would 645mm X 445 mm?*

A1: All parcels shipped by DND will be in accordance with the following configuration:

- The max size of any one side is one metre.
- The length plus girth of a parcel can't be more than two metres.
<https://www.canada.ca/en/department-national-defence/services/contact-us/write-troops/instructions-for-mailing-overseas.html>

Reference: **Annex A, STATEMENT OF WORK**
Criterion No 3.1.1 : The X-Ray machine must allow items of at least a minimum 495mm X 400 mm in size to pass through the X-Ray

Delete: in its entirety

Insert: **Annex A, STATEMENT OF WORK**
Criterion No 3.1.1 : The X-Ray machine must allow parcels to pass through the X-Ray in accordance with the following configuration:

- The max size of any one side is one metre.
- The length plus girth of a parcel can't be more than two metres.
<https://www.canada.ca/en/department-national-defence/services/contact-us/write-troops/instructions-for-mailing-overseas.html>

Q2: *Pedal to control the rate of parcel process flow Does that mean the foot pedal slows and accelerate the speed of the process flow?*

A2: Either is acceptable.

Reference: **Annex A, STATEMENT OF WORK**
Criterion No 3.1.17 : The X-Ray machine must have a foot pedal to control the rate of parcel processing flow. Once the operator steps away from the foot pedal, the X-Ray generator and X-Ray operations must stop.

Delete: in its entirety

Insert: **The X-Ray machine must have a foot pedal to control the rate of parcel processing flow or to start and stop. Once the operator steps away from the foot pedal, the X-Ray generator and X-Ray operations must stop.**

Q3: *Is the training software required on the x-ray machine, or could it be on a standalone computer?*

A3: Either is acceptable.

Reference: **Annex A, STATEMENT OF WORK**
Criterion No 3.2.17 : The X-Ray Machine should allow operators and the supervisor to perform training separate from live operations. In addition, the operator training program should allow for the X-Ray Machine to be used as a training terminal without running parcels or baggage though it.

Solicitation No. - N° de l'invitation
W6776-210009/A
Client Ref. No. - N° de réf. du client
W6776-21-0009

Amd. No. - N° de la modif.
001
File No. - N° du dossier
KIN-1-56211

Buyer ID - Id de l'acheteur
KIN930
CCC No./N° CCC - FMS No./N° VME

Reference: **Annex B, BASIS OF PAYMENT**

Delete: *Instructions: Bidders are requested to provide Firm unit prices, all inclusive, in Canadian funds, Delivered Duty Paid “DDP” Mississauga, Ontario. Prices include Shipping, Canadian customs duties and excise taxes as applicable and Taxes Extra.*

Insert: *Instructions: Bidders are requested to provide Firm unit prices, all inclusive, in Canadian funds, Delivered Duty Paid “DDP” **Trenton**, Ontario. Prices include Shipping, Canadian customs duties and excise taxes as applicable and Taxes Extra.*