

**RETURN BIDS TO:**  
**RETOURNER LES SOUMISSIONS À:**  
Bid Receiving Public Works and Government  
Services Canada/Réception des soumissions Travaux  
publics et Services gouvernementaux Canada  
800 Burrard Street, 12th floor  
800, rue Burrard, 12e étage  
Vancouver  
British Columbia  
V6Z 2V8  
Bid Fax: (604) 775-9381

## SOLICITATION AMENDMENT MODIFICATION DE L'INVITATION

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Solicitation remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'invitation demeurent les mêmes.

### Comments - Commentaires

Vendor/Firm Name and Address  
Raison sociale et adresse du  
fournisseur/de l'entrepreneur

**Issuing Office - Bureau de distribution**  
Public Works and Government Services Canada -  
Pacific Region  
800 Burrard Street, 12th floor  
800, rue Burrard, 12e étage  
Vancouver  
British C  
V6Z 2V8

<b>Title - Sujet</b> Ocean Terrace Site Reclamation	
<b>Solicitation No. - N° de l'invitation</b> EZ899-130441/A	<b>Amendment No. - N° modif.</b> 001
<b>Client Reference No. - N° de référence du client</b>	<b>Date</b> 2012-06-19
<b>GETS Reference No. - N° de référence de SEAG</b> PW-\$PWY-020-6715	
<b>File No. - N° de dossier</b> PWY-2-35050 (020)	<b>CCC No./N° CCC - FMS No./N° VME</b>
<b>Solicitation Closes - L'invitation prend fin</b> <b>at - à 02:00 PM</b> <b>on - le 2012-07-05</b>	<b>Time Zone</b> Fuseau horaire Pacific Daylight Saving Time PDT
<b>F.O.B. - F.A.B.</b> <b>Plant-Usine:</b> <input type="checkbox"/> <b>Destination:</b> <input checked="" type="checkbox"/> <b>Other-Autre:</b> <input type="checkbox"/>	
<b>Address Enquiries to: - Adresser toutes questions à:</b> Ly, Ronny(PWY)	<b>Buyer Id - Id de l'acheteur</b> pwy020
<b>Telephone No. - N° de téléphone</b> (604) 666-0043 ( )	<b>FAX No. - N° de FAX</b> (604) 775-6633
<b>Destination - of Goods, Services, and Construction:</b> <b>Destination - des biens, services et construction:</b> Parks Canada - Pacific Rim National Park Reserve - Ucluelet, B.C.	

Instructions: See Herein

Instructions: Voir aux présentes

<b>Delivery Required - Livraison exigée</b>	<b>Delivery Offered - Livraison proposée</b>
<b>Vendor/Firm Name and Address</b> <b>Raison sociale et adresse du fournisseur/de l'entrepreneur</b>	
<b>Telephone No. - N° de téléphone</b> <b>Facsimile No. - N° de télécopieur</b>	
<b>Name and title of person authorized to sign on behalf of Vendor/Firm</b> <b>(type or print)</b> <b>Nom et titre de la personne autorisée à signer au nom du fournisseur/</b> <b>de l'entrepreneur (taper ou écrire en caractères d'imprimerie)</b>	
<b>Signature</b>	<b>Date</b>

Solicitation No. - N° de l'invitation

EZ899-130441/A

Amd. No. - N° de la modif.

001

Buyer ID - Id de l'acheteur

pw020

Client Ref. No. - N° de réf. du client

File No. - N° du dossier

CCC No./N° CCC - FMS No/ N° VME

PWY-2-35050

---

Please find Addendum #1 herein and the revised Bid and Acceptance Form (BA).

All other terms and conditions remain unchanged.

Solicitation No. - N° de l'invitation

EZ899-130441/A

Client Ref. No. - N° de réf. du client

Amd. No. - N° de la modif.

001

File No. - N° du dossier

PWY-2-35050

Buyer ID - Id de l'acheteur

pw020

CCC No./N° CCC - FMS No/ N° VME

---

## BID AND ACCEPTANCE FORM (BA)

Revised June 19, 2012

### BA01 IDENTIFICATION

Ocean Terrace Site Reclamation  
Ucluelet, B.C.

### BA02 BUSINESS NAME AND ADDRESS OF BIDDER

Name: \_\_\_\_\_

Address: \_\_\_\_\_

\_\_\_\_\_

Telephone: \_\_\_\_\_ Fax: \_\_\_\_\_ PBN: \_\_\_\_\_

### BA03 THE OFFER

The Bidder offers to Canada to perform and complete the Work for the above named project in accordance with the Bid Documents for the Total Bid Amount of

\$ \_\_\_\_\_ excluding GST/HST.  
(amount in numbers)

### BA04 BID VALIDITY PERIOD

The bid shall not be withdrawn for a period of [\_30\_] days following the date of solicitation closing.

### BA05 ACCEPTANCE AND CONTRACT

Upon acceptance of the Contractor's offer by Canada, a binding Contract shall be formed between Canada and the Contractor. The documents forming the Contract shall be the contract documents identified in Contract Documents (CD).

### BA06 CONSTRUCTION TIME

The Contractor shall perform and complete the Work within **nine [9]** weeks from the date of notification of acceptance of the offer.

### BA07 BID SECURITY

The Bidder is enclosing bid security with its bid in accordance with GI09 - Bid Security Requirements of R2710T - General Instructions to Bidders.

### BA08 SIGNATURE

\_\_\_\_\_  
Name and title of person authorized to sign on behalf of Bidder (Type or print)

\_\_\_\_\_  
Signature

\_\_\_\_\_  
Date

The following changes in the tender documents are effective immediately. This addendum will form part of the contract documents.

## **1. Specifications – Section 01 11 55 – General Instructions**

### **.1 1.2 DESCRIPTION OF WORK**

- .1 Work under this Contract covers work on the Pacific Rim National Park Reserve.

**ADD:** Site 2 - Existing Park service site on the West side of the Tofino/Ucluelet Highway. Work consists of as follows; Refer to Site Plan (**Addendum 1 – SK1**).


- .1 De-construct existing **Sun Surf Watch Tower** overhead and buried in its entirety. Refer to attached (**Addendum 1 – SK2 – SK10**)
- .2 Remove all debris material as instructed in the contract documents or as otherwise instructed.
- .3 Move the concrete/wood table on to the grass area adjacent and repair disturbed grass area with top soil and turf.
- .4 All work to be in accordance to the requirements of the "Environmental Assessment Report" included as Appendix A.

## **2. Specifications – Section 01 11 55 – General Instructions**

### **.1 1.5 TIME OF COMPLETION**

- .1 Revise: Complete the project in its entirety within 9 weeks of Award of Contract.

**END OF ADDENDUM NO. 1**



ADDENDUM 1 - SK 1 (MAY 2012)



Photo 1: Full view of the Sun Surf Watch Tower at Long Beach, Tofino, BC.





Photo 2: Top Connection 1 of the steel platform showing rusting issues



Photo 3: Top Connection 2 of the steel platform showing rusting issues







Photo 4: Top Connection 3 of the steel platform showing rusting issues



Photo 5: Top Connection 4 of the steel platform showing rusting issues





Photo 6: Base Connection 1 of the steel platform showing rusting issues



Photo 7: Base Connection 2 of the steel platform showing rusting issues





Photo 8: Base Connection 3 of the steel platform showing rusting issues



Photo 9: Base Connection 4 of the steel platform showing rusting issues





Photo 10: Close up of the base connection showing advanced stage of rusting.



Photo 11: Close up of the base anchor bolts showing the complete rusting of the washers







Photo 12: Site measurement showing reduction of steel material thickness. (Original at 10mm thick)



Photo 13: Rusting of the steel beam along the length of the member.



Photo 14: Rusting of cage bars and rungs requiring repairs



Photo 15: Rusting of cage bars and rungs requiring repairs





Photo 16: Close up of the rusted cage components

