

APPENDIX 4

SITE PHOTOGRAPHS – INTERIOR



Photo 1: View of the Gereaux Island Light Station from Georgian Bay.



Photo 2: View from top of lighthouse facing south, residence building, helicopter pad, and boathouse visible.



Photo 3: View of lighthouse facing north.



Photo 4: View L.H LS-6 sample location from lighthouse third floor interior wall. Sample was found to be above criteria and is considered lead based.



Photo 5: View of teal paint in main floor stairwell, sample L.H LS-3 was found to be above criteria and is considered lead based.



Photo 6: View of residence building basement, sample R.B LS-5 (battleship grey floor paint) was found to be above criteria and is considered lead based.



Photo 7: View of peeling paint in bathroom in residence building, sample R.B LS-8 was found to be below criteria and is considered non-lead based.