

RETURN BIDS TO:
RETOURNER LES SOUMISSIONS À:
Bid Receiving Public Works and Government
Services Canada/Réception des soumissions Travaux
publics et Services gouvernementaux Canada
1713 Bedford Row
Halifax, N.S./Halifax, (N.É.)
B3J 1T3
Bid Fax: (902) 496-5016

SOLICITATION AMENDMENT MODIFICATION DE L'INVITATION

The referenced document is hereby revised; unless otherwise indicated, all other terms and conditions of the Solicitation remain the same.

Ce document est par la présente révisé; sauf indication contraire, les modalités de l'invitation demeurent les mêmes.

Comments - Commentaires

Vendor/Firm Name and Address
Raison sociale et adresse du
fournisseur/de l'entrepreneur

Issuing Office - Bureau de distribution
Acquisitions
1713 Bedford Row
Halifax, N.S./Halifax, (N.É.)
B3J 3C9

Title - Sujet REFIT FOR CCGS SPRAY	
Solicitation No. - N° de l'invitation F5561-132779/A	Amendment No. - N° modif. 001
Client Reference No. - N° de référence du client F5561-13-2779	Date 2014-01-13
GETS Reference No. - N° de référence de SEAG PW-\$HAL-403-9159	
File No. - N° de dossier HAL-3-71220 (403)	CCC No./N° CCC - FMS No./N° VME
Solicitation Closes - L'invitation prend fin at - à 02:00 PM on - le 2014-01-23	Time Zone Fuseau horaire Atlantic Standard Time AST
F.O.B. - F.A.B. Plant-Usine: <input type="checkbox"/> Destination: <input checked="" type="checkbox"/> Other-Autre: <input type="checkbox"/>	
Address Enquiries to: - Adresser toutes questions à: Brow, Theresa	Buyer Id - Id de l'acheteur hal403
Telephone No. - N° de téléphone (902) 496-5166 ()	FAX No. - N° de FAX (902) 496-5016
Destination - of Goods, Services, and Construction: Destination - des biens, services et construction:	

Instructions: See Herein

Instructions: Voir aux présentes

Delivery Required - Livraison exigée	Delivery Offered - Livraison proposée
Vendor/Firm Name and Address Raison sociale et adresse du fournisseur/de l'entrepreneur	
Telephone No. - N° de téléphone Facsimile No. - N° de télécopieur	
Name and title of person authorized to sign on behalf of Vendor/Firm (type or print) Nom et titre de la personne autorisée à signer au nom du fournisseur/ de l'entrepreneur (taper ou écrire en caractères d'imprimerie)	
Signature	Date

This amendment is raised to provide the shafting arrangement, the vessel's division 3 report and to provide bidders with pricing data sheet.

Be advised also that the Bidders Conference scheduled for Tuesday, January 14, 2014 has been cancelled. Vessel viewing is still scheduled.

E-02 – \$6000 allowance for CAT, and adjust via 1379 at end of refit.

Note: in paragraphs 3 and 5, delete “subcontractor”, and replace with “Atlantic Cat”

E-04 - \$1500 allowance for fire system re-certification

PRICING DATA SHEET - CCGS SPRAY

H-1 Services	1	\$
Para 1.1 Electrical Power Unit cost/day	\$	
Para 2.1 Gangways Cost/day	\$	
Para 3.1 Garbage Removal/Cleaning Cost/day	\$	
Para 4.1 Berthing Cost/day	\$	
Para 5.1 Shelter/Enclosure Cost/day	\$	
Para 6.1 Sea Trial Cost/hr	\$	
H-02 Tank & Void Space Inspections	2	\$
Para 2. Unit cost per litre for removal and disposal	\$	
HD-01 Docking/Undocking	3	\$
HD-02 PAINTING	4	\$
Para 1 Cost/M2 for painting	\$	
HD-03 PROPELLER SHAFTS & BEARINGS SURVEY	5	\$
HD-04 STORM VALVES AND SEA CONNECTIONS	6	\$
HD-05 UNDERWATER HULL INSPECTION -SURVEY	7	\$
E-01 STEERING GEAR INSPECTION - SURVEY	8	\$
E-02 ENGINE SERVICE	9a	
Para 1 CAT Allowance - to be adjusted	\$6,000.00	9b \$6,000.00
E-03 ANCHORS AND CHAIN INSPECTION	10	\$
E-04 FIREFIGHTING EQUIPMENT - SURVEY	11a	\$
Para 2. Fire System Re-certification allowance - to be adjusted	\$1,500.00	11b \$1,500.00
		\$
Total Cost, Taxes not included (items 1-11b)		
This is the price for the Known work in Annex I:		

Division 3 Report

Vessel Name	MV SPRAY
File Number	15382
Official Number	816536
Builder	INDUSTRIES RAYMOND INC.
IMO Number	
Dimensions: Length	14.75
Dimensions: Breadth	5.21
Dimensions: Depth	1.4
Registration Date	1995 04 21
Registration Expiry Date	2014 08 31
Builder	INDUSTRIES RAYMOND INC.
Hull/Project Number	
Gross Tonnage	42.12
Registered Tonnage	25.02
Port of Registry	OTTAWA
Propulsion Power	1070
Last Inspection	Intermediate
Last Inspected Date	2013 05 15
Last Inspection Place	Sambro, NS
Last inspected by	Munroe, James
Last inspection TCC	Atlantic Region (200)

Vessel Name: MV SPRAY

File Number: 15382

<u>Field Number</u>	<u>Occur.</u>	<u>Type / Rmk No.</u>	<u>Value</u>
-------------------------	---------------	---------------------------	--------------

Description

Section: 01 - General Information On Vessel



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Description

<u>Field Number</u>	<u>Occur.</u>	<u>Type / Rmk No.</u>	<u>Value</u>
---------------------	---------------	-----------------------	--------------

Periodic Inspection

2H0010	NR		Date: 2010 07 09 - 04 Place: Louisbourg
--------	----	--	--

Section: 20 - Main Structure

Underwater Hull Inspection

3LL040	NR		Date: 2010 03 25 - 04 Place: Petit De Grat, NS
--------	----	--	---

Section: 24 - Protection Against Sea & Load Lines

Storm Valves Inspection

3LL090	01		Date: 2010 03 19 - 04
	01	Number: 01	
	01	Location: Sb Fr No.21 Toilett Vent.	
	02	Date: 2010 03 19 - 04	
	02	Number: 02	
	02	Location: Ps/sb Fr No.13 Blg Pp Ovb	
	03	Date: 2010 03 19 - 04	
	03	Number: 01	
	03	Location: Sb Fr No.9 Fire Pp Ovb	

Sea Connections Inspection

3LL110	01		Date: 2010 03 19 - 04
	01	Number: 02	
	01	Location: Ps/sb Fr No.13 Mie's	
	02	Date: 2010 03 19 - 04	
	02	Number: 02	
	02	Location: Ps/sb Fr No.13 De-icing	
	03	Date: 2010 03 19 - 04	
	03	Number: 01	
	03	Location: Ps Fr No.8 Fire Pip	



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Description

<u>Field Number</u>	<u>Occur.</u>	<u>Type / Rmk No.</u>	<u>Value</u>
	04		Date: 2010 03 19 - 04
	04		Number: 01
	04		Location: Ps Fr No.8 De-icing
	05		Date: 2010 03 19 - 04
	05		Number: 02
	05		Location: Ps/sb Fr No.13 Blg Pp Ovb
	06		Date: 2010 03 19 - 04
	06		Number: 01
	06		Location: Ps Fr No.9 Fire Pp Ovb
Section: 26 - Steering & Manoeuvrability			
Steering Gear Components Inspection	01		Date: 2010 03 23 - 04
		4	2010 03 25
			Port rudder removed and replaced with new rudder and all associated hardware
	01		Initials: EK
	01		TCC: Port Hawkesbury
Section: 27 - Anchorage, Mooring & Towing			
Anchors Inspected	01		Date: 2010 03 23 - 04
	01		Place: Sambro, Nova Scotia
Cable or Chain Inspected	01		Date: 2010 03 23 - 04
	01		Place: Sambro, Nova Scotia
Section: 31 - Screw, Screwshafts, Bearings			
Port Tube or Tail Shaft Inspection	NR		Date: 2010 03 23 - 04
		1	Measurements taken at Boyd Babin's shop. Copy on file.



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Description

Field Number Type / Rmk No.

Occur. Value

Starboard Tube or Tail Shaft Inspection

3FF030

NR

Shaft Diameter: 69.7

Date: 2010 03 23 - 04

Measurements taken at Boyd Babin's shop. Copy on file.

Shaft Diameter: 69.3

Port Stern Bearing Inspection

3FF060

NR

Date: 2010 03 23 - 04

2 New Thordon bearings installed on Struts

2 new thordon stern bearings installed

Weardown: 000.30

Inner Port Stern Tube Inspection

3FF070

NR

Date: 2010 03 25 - 04

2010 03 25

New Thordon bearing installed

Weardown: 000.00

Starboard Stern Bearing Inspection

3FF080

NR

Date: 2010 03 25 - 04

2010 03 25

New Thordon bearing installed

Weardown: 000.00

Inner Starboard Shaft Bearing Inspection

3FF090

NR

Date: 2010 03 25 - 04

Thordon Shaft bearing installed

Weardown: 000.70

Section: 50 - Lifesaving Equipment

Inflatable LifeRaft Serviced (oldest Date)

3N0050

NR

Date: 2012 10 31 - 01

HRU expiry Dec, 2010.

Pyro-Distress Signals Manufactured(bridge)

3N0060

01

Date: 2007 01 01 - 04



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Description

<u>Field Number</u>	<u>Occur.</u>	<u>Type / Rmk No.</u>	<u>Value</u>
---------------------	---------------	-----------------------	--------------

Line Throwing Device

3N0100	01		Date Manufactured: 2005 11 30 - 04
--------	----	--	------------------------------------

Section: 51 - Fire Detection, Alarms & Extinguisher Equipment

Smothering Medium Cylinder Hydrostatic Test

3N0010	01		Date: 2006 03 31 - 12
--------	----	--	-----------------------

Smothering System Serviced

3N0090	01		Date: 2012 11 30 - 01
--------	----	--	-----------------------

Section: 60 - Electricity

Electrical System Insulation Test

3EE010	NR	1	Date: 2011 03 30 - 04 Meggar test.
--------	----	---	---------------------------------------

Vessel Name: MV SPRAY

File Number: 15382

Section: Continuous Survey Items

<u>Item</u>	<u>Description</u>	<u>Inspection Date</u>	<u>Test Date</u>	<u>Frequency</u>
-------------	--------------------	------------------------	------------------	------------------

3D - Diesel Engines

3D001

Port M/e

2013 04 22	Munroe, James	2		5
------------	---------------	---	--	---

Need oil report and PAR. JM April 22, 2013
Serviced by Caterpillar Technician. July 11, 2008

3D002

Stbd M/e

2013 04 22	Munroe, James	2		5
------------	---------------	---	--	---

Running hrs: 5595 (2008-06-27)
Need oil report and PAR. JM April 22, 2013
Serviced by Caterpillar Technician. July 11, 2008

Running hrs: 5588 (2008-06-27)



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Section: Continuous Survey Items

<u>Item</u>	<u>Description</u>	<u>Inspection Date</u>	<u>Test Date</u>	<u>Frequency</u>
3H - Auxiliaries Not Connected to Nor Driven By Main Engine				
3H001	Port Side M/e Driven Bilge Pp	2013 04 22 Munroe, James		5
3H002	St'bd Side M/e Driven Bilge Pp	2013 05 15 Munroe, James		5
3H003	Main Fire Pp On Port M/e	2013 04 22 Munroe, James	Pump replaced.	5
3H004	Port Submersible Bilge Pp	2013 04 22 Munroe, James		5
3H005	St'bd Submersible Bilge Pp	2013 04 22 Munroe, James		5
3H006	Bow Windlass	2013 04 22 Munroe, James		5
3L - Tanks				
3L001	#12 Forepeak	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L002	#10 ACC DB Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L003	#15P ACC DB Void O/B Port Aft	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L004	#15S ACC DB Void O/B Stbd Aft	2010 03 19 Rhynold, Blair	Not Accessible 2010 03 25 Kehoe, ED	4
3L005	#16P ACC DB Void O/B Port Fwd	2010 03 19 Rhynold, Blair	Not Accessible 2010 03 25	4



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Section: Continuous Survey Items

<u>Item</u>	<u>Description</u>	<u>Inspection Date</u>	<u>Test Date</u>	<u>Frequency</u>
3L006	#16S ACC DB Void O/B Stbd Fwd	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L007	#2 ACC F/O DB Port	2010 03 19 Mackenzie, Douglas J	2006 04 28 Coggins, Peter H.	4
3L008	#1 ACC F/O DB Stbd	2010 03 25 Kehoe, ED	2006 04 28 Coggins, Peter H.	4
3L009	#21P ACC Port Side Void Aft	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L010	#21S ACC Stbd Side Void Aft	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L011	#22P ACC Port Side Void Fwd	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L012	#22S ACC Stbd Side Void Fwd	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L013	#24 ACC W/Room Above Tank #11	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L014	#11 ACC W/Room DB Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L015	#17P ACC W/Room Port Side Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L016	#17S ACC W/Room Stbd Side Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L017	#9 E/R DB Centre Fwd	2010 03 23 Kehoe, ED	2010 03 25 Kehoe, ED	4
3L018	#25 E/R DB Centre Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4



Vessel Name: MV SPRAY

File Number: 15382

Section: Continuous Survey Items

<u>Item</u>	<u>Description</u>	<u>Inspection Date</u>	<u>Test Date</u>	<u>Frequency</u>
3L019	#8 E/R DB Void Aft	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L020	#14P E/R DB Void O/B Port	2010 03 25 Kehoe, ED	2010 03 25 Kehoe, ED	4
3L021	#14S E/R DB Void O/B Stbd	2010 03 25 Kehoe, ED	2010 03 25 Kehoe, ED	4
3L022	#5 E/R DB Void Port	2010 03 23 Kehoe, ED	2010 03 25 Kehoe, ED	4
3L023	#4 E/R DB Void Stbd	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L024	#13P E/R DB Void Port Aft	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L025	#13S E/R DB Void Stbd Aft	2010 03 25 Kehoe, ED	2010 03 25 Kehoe, ED	4
3L026	#3 E/R F/O DB Centre	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L027	#20P E/R Port Side Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L028	#20S E/R Stbd Side Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L029	#7 Victim Recovery DB Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L030	#19P Victim Recovery Port Side Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4
3L031	#19S Victim Recovery Stbd Side Void	2010 03 19 Rhynold, Blair	2010 03 25 Kehoe, ED	4



Division 3 Report

Vessel Name: MV SPRAY

File Number: 15382

Section: Continuous Survey Items

<u>Item</u>	<u>Description</u>	<u>Inspection Date</u>	<u>Test Date</u>	<u>Frequency</u>
3L032	#23 Steering Aft Void above No 6 DB	<u>2010 03 19</u> Rhynold, Blair	<u>2010 03 25</u> Kehoe, ED	4
3L033	#6 Steering DB Void	<u>2010 03 19</u> Rhynold, Blair	<u>2010 03 25</u> Kehoe, ED	4
3L034	#18P Steering Port Side Void	<u>2010 03 19</u> Rhynold, Blair	<u>2010 03 25</u> Kehoe, ED	4
3L035	#18S Steering Stbd Side Void	<u>2010 03 19</u> Rhynold, Blair	<u>2010 03 25</u> Kehoe, ED	4
3L036	Port M/E Sea Bay	<u>2010 03 25</u> Kehoe, ED	<u>2010 03 25</u> Kehoe, ED	4
3L037	Stbd M.E. Sea Bay	<u>2010 03 25</u> Kehoe, ED	<u>2010 03 25</u> Kehoe, ED	4
3L038	Fire Pump Sea Bay	<u>2010 03 25</u> Kehoe, ED	<u>2010 03 25</u> Kehoe, ED	4

Vessel Name: MV SPRAY

File Number: 15382

Section: Certificates List

Record of Safety Equipment for a Vessel Operating on Non-Convention Voyages SIC Number: 85-0138 Maximum Endorsements:0 Document No.:200900373200

Initial Issue	Issued / <u>Endorsed</u>	Extens. <u>Date</u>	Expiry <u>Date</u>	Short <u>Term</u>	Surveyor <u>Init/TCC</u>
	2009 08 06		2014 08 05		Munroe, James Atlantic Region



Division 3 Report

Non-Passenger Vessel < 150 Tons

SIC Number: 85-0433 Maximum Endorsements:3 Document No.:2010-041-202

	Issued / <u>Endorsed</u> 2010 07 09	Extens. <u>Date</u>	Expiry <u>Date</u> 2014 03 24	Short <u>Term</u>	Surveyor <u>Init/TCC</u> Mackenzie, Douglas J Sydney
Initial Issue					

SI7 Notes

1A0010	1	Vessels name to be painted on the bow. (Date Rectified: 2009 08 06)
2H0090	1	Crew to obtain first aid course July 22, 2009. (Date Rectified: 2009 08 06)
2J0840	1	Day shapes to be put onboard. (Date Rectified: 2009 08 06)
2N0160	1	Need to replace a fire bucket and lanyards. (Date Rectified: 2009 08 06)

No deficiencies exist

Deficiencies / Non-conformities