

DATE January 28, 2014

REFERENCE No. 1314260010-092-TM-Rev0-7000

TO Mr. Brad Thompson
Giant Mine
PWGSC (Public Works and Government Services Canada)

FROM David Caughill

EMAIL dcaughill@golder.com

PHOTOGRAPHS – GIANT MINE SOUTH POND, 2013

As part of an underground paste backfill program completed in the fall of 2013 at the Giant Mine Site in the NWT, tailings were excavated from the South Pond between October and November 2013. In general, 1 to 2 m of tailings were excavated from the north-west section of the pond. Tailings were also excavated to a similar depth along western portions of the South Pond. Several photographs are provided below of the tailings surface before and after the tailings were excavated.



Photograph 1: North end of South Pond, Looking South – July 9, 2013



Golder Associates Ltd.

500 - 4260 Still Creek Drive, Burnaby, British Columbia, Canada V5C 6C6
Tel: +1 (604) 296 4200 Fax: +1 (604) 298 5253 www.golder.com

Golder Associates: Operations in Africa, Asia, Australasia, Europe, North America and South America



Golder, Golder Associates and the GA globe design are trademarks of Golder Associates Corporation.



Photograph 2: North end of South Pond, Looking West – July 9, 2013



Photograph 3: Northwest Corner of the South Pond, Looking East, November 16, 2013

Most of the stockpiled tailings shown on the photograph have been removed since the photograph was taken.



Photograph 4: Northwest Portion of the South Pond, south of Photo 3, Looking East, November 16, 2013

Most of the stockpiled tailings shown on the photograph have been removed since the photograph was taken.

GOLDER ASSOCIATES LTD.

ORIGINAL SIGNED

Dave Caughill, M.Sc., P.Eng.
Associate, Senior Geotechnical Engineer

DC/JAH/ja

\\golder.gds\gal\burnaby\final\2013\1426\13-1426-0010\1314260010-092-tm-rev0-7000\1314260010-092-tm-rev0-7000-giant south pond photographs 2013 28jan_14.docx