













STORM HAZARDOUS AND NON-HAZARDOUS INVENTORY TABLE Volume (m³ and drums)¹ APEC # APEC Description Material Classification Material Type **Material Description** Condition 1 core rack, Mill: 2 wood boxes: 0.2 m x 0.4 m x 0.15 m. Gravel box: 0.2 m x 0.4 m x 0.15 m, Chute: 0.2 m wide, 0.03 m thick, 10 m long. Wood Debris 0.1 Unpainted Two trenches and former mill Non-Hazardous Metal pipe: 1 m long, cans
Plastic bags
2 small batteries Rusted Intact Decaying Metal Debris 2 Wood logs North Camp Ruin (1 former building) Wood Debris Unpainted Non-Hazardous Metal Debris 0.5 Stove, buried food cans. Rusted West of 3: Wood log with claim sticker. 0.1 Wood log with claim sticker, A58543 N/A Non-Hazardous Wood Debris Unpainted South Camp Ruin (3 former buildings and 1 dump) 3 Buildings: All wood logs, 1m high, 3.3 m x 3.3 m. Wood Debris Unpainted Non-Hazardous Metal Debris Dump: 20 rusted tin cans.

South Camp ruin (3 former buildings APEC 4 & 1 dump)

wooden box with gravel

2 trenches & APEC 2

high water mark

**FINAL** 

O - HAZMAT SAMPLE LOCATION

CP • - CONTROL POINT

D - DRUMS
M - METAL DEBRIS
W - WOOD DEBRIS
V - VEHICLE



REMEDIATION ACTION PLAN FOR 7 ABANDONED MINE SITES, NT

STORM MINE - AREA 1: HAZARDOUS AND NON-HAZARDOUS MATERIALS



FIGURE SM 3 1

