GEMTEC
Consulting Engineers and Scientists

BOREHOLE LOGS

Client	Public Works & Government Services Canada	Proj No. 4735.59	BOREHOLE BH15-1
Project	Structure Replacement, Miller Brook Wharf	Date Drilled 2015/05/27	Page 1 of 2
Location	Milebrook Wharf Road, Salmon Beach, NB		
Ground Level, m 3.36	Datum: Chart	Logged By ED	

Unconfined Compression ○ Field Vane Test ■ Pocket Penetrometer ◎ Remoulded
Undrained Shear Strength - kPa
Water Content & Atterburg Limits
Dynamic Penetration Test, blows/0.3m
Standard Penetration Test, blows/0.3m

DEPTH m	No	TYPE	N (RQD)	REC (mm)	DESCRIPTION
0	1	S	14	350	Brown gravel and sand, trace silt: FILL
	2	S	100	170	
1	3	S	17	330	- trace wood
	4	S	16	270	
2	5	S	15	140	
	6	S	23	60	
3	7	S	21	460	
	8	S	4	80	- trace black wood (4.22, -0.86) Loose black organic SAND and GRAVEL, trace silt
4	9	S	9	80	
	10	S	5	180	
5	11	S	6	0	
	12	S	12	310	(5.13, -3.78)
6	13	S	18	330	Medium compact reddish brown silty sand, trace gravel: TILL
	14	S	100	470	(6.51, -5.15)
7	15	NQ		580	Grey brown Mudstone: BEDROCK
	16	NQ		1500	- siltstone cobbles throughout
8					
	17	NQ		1300	
9					
10					
11					

GEOTG 473599-GPJ GEMTEC 2004.GDT 10/09/15

GEMTEC
Consulting Engineers and Scientists

BOREHOLE LOGS

Client	Public Works & Government Services Canada	Proj No. 4735.59	BOREHOLE BH15-1
Project	Structure Replacement, Miller Brook Wharf	Date Drilled 2015/05/27	Page 2 of 2
Location	Milebrook Wharf Road, Salmon Beach, NB		
Ground Level, m 3.36	Datum: Chart	Logged By ED	

Unconfined Compression ○ Field Vane Test ■ Pocket Penetrometer ◎ Remoulded
Undrained Shear Strength - kPa
Water Content & Atterburg Limits
Dynamic Penetration Test, blows/0.3m
Standard Penetration Test, blows/0.3m

DEPTH m	No	TYPE	N (RQD)	REC (mm)	DESCRIPTION
11					
12	18	NQ		630	- compressive strength of core: 61.4MPa indicating strong rock Grey brown Mudstone: BEDROCK
13					
14	19	NQ		1524	(15.24, -11.88)
15					End of BH 15-1 at 15.24 meters below existing ground surface Water inferred at 1.37 meters below existing ground surface at the time oh drilling

GEOTG 473599-GPJ GEMTEC 2004.GDT 10/09/15

GEMTEC
Consulting Engineers and Scientists

BOREHOLE LOGS

Client	Public Works & Government Services Canada	Proj No. 4735.59	BOREHOLE BH15-2
Project	Structure Replacement, Miller Brook Wharf	Date Drilled 2015/05/27	Page 1 of 2
Location	Milebrook Wharf Road, Salmon Beach, NB		
Ground Level, m 3.53	Datum: Chart	Logged By ED	

Unconfined Compression ○ Field Vane Test ■ Pocket Penetrometer ◎ Remoulded
Undrained Shear Strength - kPa
Water Content & Atterburg Limits
Dynamic Penetration Test, blows/0.3m
Standard Penetration Test, blows/0.3m

DEPTH m	No	TYPE	N (RQD)	REC (mm)	DESCRIPTION
0	1	S	100	200	Brown gravel and sand, trace silt: FILL
					(0.48, 3.05) Breakwater boulders: FILL
1					
2					
3	3	S	36	210	(3.05, 0.48) Dense to medium compact brown GRAVEL and SAND, trace silt
	4	S	25	220	
4	5	S	100	150	- trace cobbles from 4.77 meters to 6.71 meters
5					
6	6	S	2	0	
	7	S	7	610	- increase amount of silt
7					(7.64, -4.11)
8	8	S	16	500	Medium compact reddish brown sandy silt, some gravel: TILL
	9	S	19	240	
9	10	S	30	420	(9.45, -5.92)
10	11	S	100	100	Grey brown Mudstone: BEDROCK
	12	NQ		380	
11	13	NQ		1420	

GEOTG 473599-GPJ GEMTEC 2004.GDT 10/09/15

GEMTEC
Consulting Engineers and Scientists

BOREHOLE LOGS

Client	Public Works & Government Services Canada	Proj No. 4735.59	BOREHOLE BH15-2
Project	Structure Replacement, Miller Brook Wharf	Date Drilled 2015/05/27	Page 2 of 2
Location	Milebrook Wharf Road, Salmon Beach, NB		
Ground Level, m 3.53	Datum: Chart	Logged By ED	

Unconfined Compression ○ Field Vane Test ■ Pocket Penetrometer ◎ Remoulded
Undrained Shear Strength - kPa
Water Content & Atterburg Limits
Dynamic Penetration Test, blows/0.3m
Standard Penetration Test, blows/0.3m

DEPTH m	No	TYPE	N (RQD)	REC (mm)	DESCRIPTION
11					Grey brown Mudstone: BEDROCK
12	14	NQ		1520	- siltstone cobbles throughout
13					
14	15	NQ		915	(14.53, -11.00)
					End of BH 15-2 at 14.53 meters below existing ground surface Water inferred at 3.05 meters below existing ground surface at the time oh drilling

GEOTG 473599-GPJ GEMTEC 2004.GDT 10/09/15

GEMTEC
Consulting Engineers and Scientists

BOREHOLE LOGS

Client	Public Works & Government Services Canada	Proj No. 4735.59	BOREHOLE BH15-3
Project	Structure Replacement, Miller Brook Wharf	Date Drilled 2015/05/28	Page 1 of 2
Location	Milebrook Wharf Road, Salmon Beach, NB		
Ground Level, m 1.94	Datum: Chart	Logged By ED	

Unconfined Compression ○ Field Vane Test ■ Pocket Penetrometer ◎ Remoulded
Undrained Shear Strength - kPa
Water Content & Atterburg Limits
Dynamic Penetration Test, blows/0.3m
Standard Penetration Test, blows/0.3m

DEPTH m	No	TYPE	N (RQD)	REC (mm)	DESCRIPTION
0	1	S	2	220	Very loose to medium compact brown gravelly SAND, trace silt
	2	S	16	400	
1	3	S	19	120	(1.12, 0.82) Medium compact reddish brown SAND and GRAVEL, trace silt
	4	S	14	400	
2	5	S	2	610	(2.89, -0.95)
	6	S	1	610	Very loose to loose grey brown organic sandy silt, trace gravel
3	7	S	2	600	- trace wood
	8	S	2	0	
4	9	S	4	610	- organic silt from 5.18 meters to 5.33 meters
	10	S	10	470	(5.85, -3.91) - organic silt from 5.79 meters to 5.85 meters
5	11	S	13	480	Medium compact reddish brown sandy silt, trace gravel: TILL
	13	NQ		50	(6.79, -4.84)
6	12	S	100	70	Grey brown Mudstone: BEDROCK
	14	NQ		60	- compressive strength of core: 59.8MPa indicating strong rock - compressive strength of core: 60.7MPa indicating strong rock
7					
8	15	NQ		1420	- siltstone cobbles throughout
9					
10					
11	16	NQ		1520	

GEOTG 473599-GPJ GEMTEC 2004.GDT 10/09/15

GEMTEC
Consulting Engineers and Scientists

BOREHOLE LOGS

Client	Public Works & Government Services Canada	Proj No. 4735.59	BOREHOLE BH15-3
Project	Structure Replacement, Miller Brook Wharf	Date Drilled 2015/05/28	Page 2 of 2
Location	Milebrook Wharf Road, Salmon Beach, NB		
Ground Level, m 1.94	Datum: Chart	Logged By ED	

Unconfined Compression ○ Field Vane Test ■ Pocket Penetrometer ◎ Remoulded
Undrained Shear Strength - kPa
Water Content & Atterburg Limits
Dynamic Penetration Test, blows/0.3m
Standard Penetration Test, blows/0.3m

DEPTH m	No	TYPE	N (RQD)	REC (mm)	DESCRIPTION
11					Grey brown Mudstone: BEDROCK
12					(12.19, -10.25)
					End of BH 15-3 at 12.19 meters below existing ground surface Water inferred at 0.61 meters below existing ground surface at the time oh drilling

GEOTG 473599-GPJ GEMTEC 2004.GDT 10/09/15

NEW STEEL H-PILE SCHEDULE
BORDEREAU DES NOUVEAUX PIEUX EN H

PILE No. *No. DE PIEU*	SUPPLIED LENGTH (m) *LONGUEUR FOURNIE (m)*	TIP ELEVATION (m) *ÉLÉVATION POINTE (m)*	LENGTH PLACED IN WORK (m) *LONGUEUR PLACER DANS LES TRAVAUX (m)*	BLOWS/LAST 25mm *COUPS/DERNIER 25mm*
30 A	12.20			
30 B	↓			
31 A				
31 B				
32 A				
32 B				
33 A				
33 B				
34 A				
34 B				
35 A				
35 B				
36 A				
36 B				
37 A				
37 B				
38 A				
38 B				
39 A				
39 B				
40 A				
40 B				
41 A				
41 B				
42 A				
42 B				
43 A				
43 B				
44 A				
44 B				
45 A				
45 B				
46 A				
46 B				
47 A				
47 B				
48 A				
48 B				
49 A				
49 B				
50 A	↓			
50 B	12.20			

Public Works and Government Services Canada / Travaux Publics et Services gouvernementaux Canada

CY Boucher Eng. & Const. Ltd.
Dieppe, N.B.
Tel.: (506)854-4233
Fax.: (506)855-6544
e-mail: cyb@nbnet.nb.ca

REGISTERED PROFESSIONAL ENGINEER
Province of New Brunswick
#M4875
Claude Boucher
SIGNATURE
December 29, 2015
DATE
Province du Nouveau-Brunswick
INGÉNIEUR / IMMATRICULÉ

revisions		date
1	FOR TENDER / POUR SOUMISSION	12/29/2015

project / projet

TRAINING WALL RECONSTRUCTION 401
RECONSTRUCTION DU MUR DE DIRECTION 401
MILLER BROOK, NB
COMTÉ DE GLOUCESTER COUNTY

drawing / dessin

BOREHOLE RECORDS AND PILE SCHEDULE
RECORDS DE FORAGE ET BORDEREAU DE PIEU

designed CY BOUCHER ENG & CONST. LTD/conçu
date DECEMBER/DÉCEMBRE 2015
drawn P. LEBLANC / dessiné
date DECEMBER/DÉCEMBRE 2015
approved / approuvé
date
Tender / Soumission
PWGSC Project Manager / Administrateur de projets TPSGC
project number / no. du projet
R.075620.001
drawing no. / no. du dessin
M8 of/de M8

PWGSC B1 (2004)

E-DRM/GDD-E: 527793 Version 1