

APPENDIX 5
Site Photographs



Picture 1: East Headlands location looking West



Picture 2: East Headlands location looking East at the Beach Area.



Picture 3: East side of the East Headland at the Beach. Note the stock pile of sandy material.



Picture 4: East Headland site looking South at the North Edge.



Picture 5: East Headland site looking South.



Picture 6: East Headland site looking East.



Picture 1: From the Parkette on the East Pier, looking South West across the river at the West Pier looking towards Work Areas 1.



Picture 2: From the Parkette on the East Pier, looking West across the river at Work Area 2 on West Pier.



Picture 3: From the Parkette on the East Pier, looking South across the river at the West Pier looking towards Work Areas 1.



Picture 4: From the Parkette on the East Pier, looking West across the river towards Work Area 1 of West Pier.



Picture 5: Looking North along the West Pier.



Picture 6: Looking North at Work Areas 2 on the West Pier.



Picture 7: Looking South along the West Pier from Work Area 1 with the Silos in the background (silos have been removed).



Picture 1: General view of the North end of West Pier lands in location of Work Area 2.



Picture 2: Looking South East at West Pier with Work Area 2 and Work Area 1 in the background.



Picture 3: Looking South at the West Pier Area. Looking at Work Area 2 with Work Area 1 behind/beside.



Picture 4: Looking South at West Pier Work Area 2. Silos in background have been removed.



Picture 5: Looking North along the West Pier looking at Work Area 1.



Picture 6: Looking North along the West Pier at Work Area 2.



Picture 7: Looking North East at the West Pier looking at Work Area 2 with Bridge Street bridge in the background.