

Solicitation No. - N° de l'invitation  
F2930-160024/A  
Client Ref. No. - N° de réf. du client  
131-23620-00

Amd. No. - N° de la modif.  
004  
File No. - N° du dossier  
PWL-6-39076

Buyer ID - Id de l'acheteur  
pwl012  
CCC No./N° CCC - FMS No/ N° VME

---

#### Questions and Answers:

##### 1. Section 01 11 03, 3.4 Preconstruction Survey & 3.5 Post Construction Survey

Question: Are these same surveys that are mentioned in Section 31 09 00, Monitoring?  
If no, please explain differences.

R1 Yes, these are the same.

##### 2. Section 31 23 33.01, 1.2.1 & .2 and Section 31 62 00, 1.4.1 & .2

A subsurface investigation report and a geotechnical report are mentioned as being attached to the documents.  
There is no attachment of appendix. Please provide a copy for our review.

R2 See attachments 16, 17, 18 & 19.