



Photo 1: View of MDZ prior to, during and six months following remediation in 2014-2015.



Photo 2: View of MDZ prior to, during and six months following remediation in 2014-2015.



Appendix C – Tender Specifications
 Wilmer Marsh Unit Remediation Site
 Wilmer, BC

SITE PHOTOGRAPHS

Project No: 219.05112.00013



Photo 3: View of MDZ prior to, during and six months following remediation in 2014-2015.



Photo 4: Test pitting in MDZ in June 2016.



SITE PHOTOGRAPHS

Appendix C – Tender Specifications
 Wilmer Marsh Unit Remediation Site
 Wilmer, BC

Project No: 219.05112.00013



Photo 5: Test pitting with all-terrain excavator (spider hoe) in June 2016.



Photo 6: Off-site Soil and Debris Management Facility adjacent to Site (2014-2015).



SITE PHOTOGRAPHS

Appendix C – Tender Specifications
 Wilmer Marsh Unit Remediation Site
 Wilmer, BC

Project No: 219.05112.00013



Photo 7: Permanent diversion ditches installed along trail.



Photo 8: Biodegradable erosion control blanket.



Appendix C – Tender Specifications
Wilmer Marsh Unit Remediation Site
Wilmer, BC

SITE PHOTOGRAPHS

Project No: 219.05112.00013



Photo 9: Wildlife tree observed south of the trail.



Photo 10: Abandoned badger burrow observed along upper part of trail (at red arrow).



Appendix C – Tender Specifications
Wilmer Marsh Unit Remediation Site
Wilmer, BC

SITE PHOTOGRAPHS

Project No: 219.05112.00013