

66 & 68 Alder Drive			
Building description: Duplex, approximately 248 m ² (both sides).			
Location	Material	Estimated Quantity	Notes
Asbestos			
Throughout building	Gypsum board and ACM joint compound	760 m ²	-
Various locations	Vinyl roll flooring	220 m ²	Underneath surface layers of flooring
Ceilings throughout building	Texture ceiling finish (ceiling stipple)	435 m ²	-
Roof	Roofing materials including ACM mastic	307 m ²	-
Ozone Depleting Substances			
Kitchen areas	ODS (refrigerator)	2	-
Mercury			
Living room of 66 Alder	Mercury containing thermostat	1	-
Throughout building	Fluorescent lamps	10	-
Lead			
Door Trim	Lead containing paint (above total, below TCLP)	520 lineal meters	-
Exterior crawlspace door	Lead containing paint (above total, below TCLP)	5 m ²	-

15 Nanuk Drive			
Building description: Detached residential, approximately 137 m ² .			
Location	Material	Estimated Quantity	Notes
Asbestos			
Dining room and lower level landing	Vinyl floor tiles	25 m ²	-
Master bedroom and adjoining bedroom	Vinyl roll flooring	16 m ²	Underneath surface layers of flooring
Throughout building	Gypsum board and ACM joint compound	496 m ²	-
Attic	Vermiculite and fibreglass insulation	60 m ²	-
Mercury			
Lower level	Mercury containing thermostat	1	-
Ozone Depleting Substances			
Kitchen	ODS (refrigerator)	1	-
Lead			
Exterior, front deck decking	Lead containing paint (above total, above TCLP)	50 m ²	-
Living room, stairwell and NE second floor room (beige and cream), walls	Lead containing paint (above total, below TCLP)	343 m ²	-
Northwest and southwest rooms (white), walls	Lead containing paint (above total, below TCLP)	70 m ²	-
Ceiling paint (white) throughout building	Lead containing paint (above total, below TCLP)	117 m ²	-
Second floor door trim (white, cream, salmon, light blue)	Lead containing paint (above total, below TCLP)	195 lineal m	-

18 Camsell Place			
Building description: Detached residential, approximately 119 m ² .			
Location	Material	Estimated Quantity	Notes
Asbestos			
Crawlspace	Cementitious pipe and coupler	2 m	-
Throughout building	Gypsum board and ACM joint compound	496 m ²	-
Attic	Vermiculite and fiberglass insulation	55 m ²	-
Mercury			
Living room	Mercury containing thermostat	1	-
Lead			
Exterior decking	Lead containing paint (above total, above TCLP)	65 m ²	-
Exterior deck railing and trim	Lead containing paint (above total, above TCLP)	327 lineal m	-
Ceiling paint (white)	Lead containing paint (above total, below TCLP)	109 m ²	-
Living room and master bedroom (beige), walls	Lead containing paint (above total, below TCLP)	82 m ²	-
Main floor and stairwell (cream, light blue, beige), walls	Lead containing paint (above total, below TCLP)	203 m ²	-
South room on second floor (beige, cream, salmon, light blue), walls	Lead containing paint (above total, below TCLP)	10 m ²	-
Interior trim (door trim, baseboards, white)	Lead containing paint (above total, below TCLP)	220 lineal m	-

221 Mackenzie Road			
Building description: Detached residential, approximately 119 m ² .			
Location	Material	Estimated Quantity	Notes
Asbestos			
Front entrance	Vinyl floor tiles	43 m ²	-
Washroom	Vinyl roll flooring	3.75 m ²	Under subfloor
Throughout building	Gypsum board and ACM joint compound	496 m ²	-
Crawlspace	Cementitious pipe and coupler	3 m	-
Attic	Vermiculite and fibergalss insulation	55 m ²	-
Mercury			
Main floor	Mercury containing thermostat	1	-
Ozone Depleting Substances			
Kitchen	ODS (refrigerator)	1	-
Lead			
Exterior decking	Lead containing paint (above total, above TCLP)	46 m ²	-
Exterior deck railings	Lead containing paint (above total, below TCLP)	304 lineal m	-
Exterior door to crawlspace	Lead containing paint (above total, above TCLP)	1.2 m ²	-
Dining room exterior wall (beige and blue), wall	Lead containing paint (above total, below TCLP)	60 m ²	-
Back entrance and shelf (beige and light green), shelf and walls	Lead containing paint (above total, below TCLP)	30 m ²	-

72 Franklin Avenue			
Building description: Warehouse, approximately 285 m ² .			
Location	Material	Estimated Quantity	Notes
Mercury			
Building interior	Fluorescent lamps	Unknown	In storage
Lead			
Double exterior doors - three sets (grey, green, white, grey)	Lead containing paint (above total, above TCLP)	10.8 m ²	-
Exterior wood siding (light blue, dark blue)	Lead containing paint (above total, above TCLP)	480 m ²	-
Front deck (light blue, dark blue)	Lead containing paint (above total, below TCLP)	22 m ²	-

74B Franklin Avenue			
Building description: Trade shop, approximately 236 m ² .			
Location	Material	Estimated Quantity	Notes
Asbestos			
Throughout building	Pipe fitting insulation	25 fittings	-
	Cementitious wall panelling	34 m ²	-
Mercury			
Main floor	Fluorescent lights	160 bulbs	-
Lead			
Front deck, underside / stairs (blue with orange)	Lead containing paint (above total, above TCLP)	43 m ²	-
Main doors	Lead containing paint (above total, below TCLP)	4.7 m ²	-