
Questions and Answers:

Q1. Concerning the site visit, was there any report done after the visit and a list of onsite contractor who assist

A1. The annexes contain all the background reports

ATTENDANCE REGISTER / REGISTRE DES PRÉSENCES

COMPANY NAME / NOM D'ENTREPRISE	PRINT NAME / NOM EN LETTRES MOULÉES
NANZU DEMOLATION AND ENVIRONMENTAL LTD	James Firth
Allen Services and Contracting	Vince Brown
Enviro-Vac Division of Paragon Remediation Group Ltd.	Phillip Mallen
Nappaq Construction	Scott Goupin

Q2. Do the piles have to removed?

A2. Piles fall under 1.2.1.1 in Section 31 23 33.01 under common excavation quantities and is further defined in Section 1.4.1.1 which states that any common materials would be removed to a depth of 300mm below ground elevation, or as directed by Departmental Representative.