



Photo 1: View from the Bioremediated Soil Storage Area looking west towards LTF cell #2. The sumps in LTF #1 and LTF #2 can be seen central right.



SITE PHOTOGRAPHS

Whitehorse Airport LTF – 2017 Specifications
Whitehorse Airport, Yukon
Whitehorse, Yukon

Project No: 205.03866.00000



Photo 2: View from the Bioremediated Soil Storage Area showing LTF 1 located on the northwest section of the work area.



SITE PHOTOGRAPHS

Whitehorse Airport LTF – 2017 Specifications
Whitehorse Airport, Yukon
Whitehorse, Yukon

Project No: 205.03866.00000



Photo 3: View of LTF 1 and 2 sumps with water for discharge.



SITE PHOTOGRAPHS

Whitehorse Airport LTF – 2017 Specifications
Whitehorse Airport, Yukon
Whitehorse, Yukon

Project No: 205.03866.00000



Photo 4: View of LTF 3 located on the southeast section of the work area.



SITE PHOTOGRAPHS

Whitehorse Airport LTF – 2017 Specifications
Whitehorse Airport, Yukon
Whitehorse, Yukon

Project No: 205.03866.00000



Photo 5: View of bioremediated soil stockpile area.



Whitehorse Airport LTF – 2017 Specifications
Whitehorse Airport, Yukon
Whitehorse, Yukon

SITE PHOTOGRAPHS

Project No: 205.03866.00000