

Part 1 General**1.1 DEFINITIONS**

- .1 Information Documents means information of any type and in any form, related to the Project and identified in this Section as such.

1.2 USE OF AND RELIANCE UPON INFORMATION DOCUMENTS

- .1 Information Documents are made available for the purpose of providing information available to the Owner.
- .2 Information Documents shall not be considered a representation or warranty that information contained therein is accurate, complete or appropriate.
- .3 Contractor to interpret and draw its own conclusions about Information Documents and is encouraged to obtain specialist advice with respect thereto. The Consultant assumes no responsibility for such interpretations and conclusions.
- .4 Information contained in Information Documents may be time sensitive and dates shall be considered when interpreting Information Documents.
- .5 Contractor may rely upon the data contained in Information Documents or parts thereof, which are specifically incorporated into Contract Documents by means of copying, transcribing or referencing, but shall draw his own conclusions from such data and shall not rely on opinions or interpretations contained therein.

1.3 PHOTOGRAPHIC INFORMATION DOCUMENTS

- .1 Photographs of Existing Building: The following sheets of photographs are hereby incorporated into the Contract Documents in their entirety.
 - .1 Photographs of Existing Building (15 pages)
- .2 Photographs are referenced from Drawing ASK03 – Photograph Locations.

Part 2 Products**2.1 NOT USED**

- .1 Not Used.

Part 3 Execution**3.1 NOT USED**

- .1 Not Used.

END OF SECTION



Photograph 1. – View of main entrance from southeast



Photograph 2. – Main entrance on south elevation



Photograph 3. A+B - Views of east wall of building. Note hood, conduit and fuel line.



Photograph 4. – Views of north wall and north entrance



Photograph 5. – Views of building from northeast corner



Photograph 6. – North section of west elevation



Photograph 7. – Central section of west elevation



Photograph 8. A+B – South, west and north walls at deck on west side of building



Photograph 9. – View of wall below deck on west elevation




Photograph 10. – Southern section of west elevation (main floor)



Photograph 11. – Southern section of west elevation (lower level)



Photograph 12. – View of building from south



Photograph 13. – View of building from south



Photograph 14. – Overall view of penthouse and roof surface from northwest prior to siding removal.



Photograph 15. – Typical exterior receptacle



Photograph 16. A+B – Typical exterior luminaire, emergency lighting, hose bibb, and small hood



Photograph 17. – Existing barrier-free operator at main entrance



Photograph 18. – Existing satellite dish support between GLs T+W and 9 and 11.



Photograph 19. – View of existing roof at cut test completed between GLs Q and R and 3 and 4.



Photograph 20. – Cut test along GL J between 4 and 5.



Photograph 21. – Cut test at base of wall at roof at GL K+5. On right is galvanized flashing support.



Photograph 22. – Cut test at clerestory windows along GL L.



Photograph 23. – View of penthouse from southwest corner during demolition of siding



Photograph 24. – View of penthouse from northwest corner during demolition of siding



Photograph 25. – Penthouse north wall



Photograph 26. – Penthouse west wall



Photograph 27. – Penthouse south wall



Photograph 28. - View of garage from southwest corner



Photograph 29. - View of garage from southeast corner



Photograph 30. - View of garage from northwest corner