



Invitation to Tender (ITT)
Sloped Sill Repair
Reference #: NGC115433
Buy and Sell Reference #: PW-18-00835718
August 17, 2018

ADDENDA # 1

This Addendum forms part of the contract documents and is to be read, interpreted, and coordinated with all other parts. The cost of all contained herein is to be included in the contract sum. Acknowledge receipt of this Addendum by inserting its number and date on the Tender Form, specifically article G.2.

1. From the meeting that we had, I recall your project manager stating that the fire watch was provided by the gallery unless we were doing hot work (soldering). Now looking at the specs I see otherwise at section 01351 – 1.5.3.1. Could you please clarify that?

NGC Response: The contractor is to provide a fire watch when any hot work is being performed. The contractor is responsible for fire watch for one hour after the work is finished. The remaining fire watch (3 hours) will be performed by the Gallery's security staff.

2. Is it possible to perform the work in the fall of 2018 rather than starting in January of 2019 as indicated in the general requirements? We could provide an optional price.

NGC Response: No