

Attachment A – Select Photos of Debris (Neegan-Burnside, 2017)

Site 2A (Waste Oil Pit #1)



**Photo 6: SITE 2A - Garbage dumped in area where Waste Oil Pit #1 is located.**



**Photo 10: SITE 2A - Garbage next to potential ridge/berm of perimeter of Waste Oil Pit #1.**



Site 2C (Waste Oil Pit #3)



**Photo 2: Trailer and old cars on west side of Lane C, beside path that leads to Oil Pit #3.**