

Annex B
Photo Log for Site
X16-X17



Photograph 1: Looking southeast at Sites X16 and X17, circa 2009. Culvert and buildings are no longer present.



Photograph 2: Looking south, at the access to the former Alaska Highway alignment. Current highway alignment is visible on the right.



Photograph 3: Washout #1 looking southeast (8m wide x 3m deep).



Photograph 4: Washout #1 looking south.



Photograph 5: Washout #2 looking south (5m wide x 1m deep).



Photograph 6: Washout #2 looking southeast.



Photograph 7: Washout #3 looking north (12m wide x 2m deep).



Photograph 8: Washout #3 looking east towards X16.



Photograph 9: Washout #3 looking southeast.