

June 29, 2021 Reference No.11230442-01

WSP Canada Inc. 294 Rink Street, Suite 103 Peterborough, ON K9J 2K2

Attention: Mr. Stephen Clark, M.Sc., P.Eng.

Re: Concrete Core Investigation

15M-00675-03 Boundary Road Bridge, Trent Severn Waterway – Upstream of Lock 37

Summary of Concrete Core Test Results				
Core Data	Client Core No.	Core 1	Core 2	Core 3
	GHD Core No.	CST-21-264	CST-21-265	CST-21-266
	Photo:	Photo 1A & B	Photo 2A & B	Photo 3A & B
	Core Location	Close to Center of Pier	About Halfway to Ring of Anchor Studs on Alignment of Bridge	Just Inside the Anchor Stud Ring
	Depth of Core	20.25" to 28"	17.5" to 24.5"	0.5" to 7.75"
	Compressive Strength of Concrete Cores			
	Corrected Strength (MPa)	18.5	19.2	13.7
	Length / Diameter Ratio	1.98	1.90	1.81
Remarks	Testing Information: Compressive Strength Testing of Concrete Cores as per LS-410 / CSA A23.2-14C. A correction factor was applied to cores with a L/D Ratio of <2 as per LS-410 / CSA A23.2-14C. Depths from surface of core.			

Joe Sullane

Joe Sullivan, Laboratory Supervisor





Photo 1A - Core No. 1 Pre-Compression



Photo 1B - Core No. 1 Post Compression



Photographs
Client Project No.: 15M-00675-03
Structure: Boundary Road Bridge – Trent Severn Waterway Upstream of Lock 37 Date of Test: June 28, 2021 GHD | Compressive Strength CSA A23.2-14C | 11230442-01 | Page 1



Photo 2A - Core No. 2 Pre-Compression



Photo 2B - Core No. 2 Post Compression



Photographs
Client Project No.: 15M-00675-03
Structure: Boundary Road Bridge – Trent Severn Waterway Upstream of Lock 37 Date of Test: June 28, 2021 GHD | Compressive Strength CSA A23.2-14C | 11230442-01 | Page 2



Photo 3A – Core No. 3 Pre-Compression



Photo 3B - Core No. 3 Post Compression



Photographs
Client Project No.: 15M-00675-03
Structure: Boundary Road Bridge – Trent Severn Waterway Upstream of Lock 37 Date of Test: June 28, 2021 GHD | Compressive Strength CSA A23.2-14C | 11230442-01 | Page 3